## **Civil Aviation Authority**



MANDATORY PERMIT DIRECTIVE

Number: 2012-003

Issue date: 04 October 2012

In accordance with 22(1) of Air Navigation Order 2009 as amended the following action required by this Mandatory Permit Directive (MPD) is mandatory for applicable aircraft registered in the United Kingdom operating on a UK CAA Permit to Fly.

Applicability:CT2K andReason:There ha imbalanceThe aircra leading e dihedral)The aircra leading e dihedral)states, the of fuel fee aircraft is tanks in oEffective Date:04/10/201Compliance/Action:Compliance1.Within action 131.2.Within (whic accord 3.	Type/Model Designation(s): CT2K and CTSW Aircraft		
Applicability:CT2K and CT2K and There ha imbalanceReason:There ha 	Fuel System – Engine Fuel Feed		
Reason:       There had imbalance         The aircrate leading edihedral) is states, the of fuel feed aircraft is tanks in or       States, the of fuel feed aircraft is tanks in or         Effective Date:       04/10/201         Compliance/Action:       Compliance/Action:         1. Within action 131.       1. Within action 131.         2. Within (whic accord 131.       1. Within 131.         3. If dur       3. If dur	P&M Aviation		
imbalance imbalance The aircra leading e dihedral) states, the of fuel fee aircraft is tanks in o Engine p approach not be pos Effective Date: 04/10/201 Compliance/Action: Compliance 1. Within action 131. 2. Within (whic accor 3. If dur	CT2K and CTSW		
Compliance/Action: Compliance/Action: 1. Within action 131. 2. Within (whic accord 3. If dur	There have been reports of engine failure as a result of fuel tank imbalance and consequent loss of fuel feed. The aircraft have a two tank fuel system, with a tank located in the leading edge section of each wing. The wing is relatively flat (low dihedral) such that if the aircraft is flown with one wing low at low fuel states, then that tank may not feed. If the other tank is empty then loss of fuel feed to the engine may occur. It is therefore important that the aircraft is flown to ensure fuel quantities are balanced across the two tanks in order to maintain uninterrupted fuel feed, particularly during approach flight phases close to the ground, where engine recovery may not be possible, is an unsafe condition that requires corrective action.		
<ol> <li>Within action 131.</li> <li>Within (whic according 3. If dur</li> </ol>	04/10/2012		
ENSURE COMPLIANCE WITH TH	<ul> <li>actions required in accordance with sub-paragraphs 1) to 7) of SB 131.</li> <li>Within 12 months and thereafter annually or at 100 hours intervals (whichever occurs earliest), carry out the checks required in accordance with sub-paragraph 8) of SB 131.</li> </ul>		
Reference Publications: P&M Aviation Service Bulletin 131 Issue 1			

**Civil Aviation** 

Authority

Remarks:	1.	This MPD was posted on 26 July 2012 as PMPD 12-01 for consultation until 25 August 2012. Enquiries regarding this Mandatory Permit Directive should be referred to: Airworthiness, Evaluation & Surveillance, Civil Aviation Authority, Safety Regulation Group, Aviation House, Gatwick Airport South, West Sussex RH6 0YR.		
	2.			
	Tel: +44 (0)1293 573146 Fax: +44 (0)1293 573		Fax: +44 (0)1293 573976	
	E-mail: department.certification@caa.co.uk			