

Civil Aviation Authority

EMERGENCY MANDATORY PERMIT DIRECTIVE



Number: 2016-011-E

Issue date: 23 November 2016

In accordance with Article 41(1) of The Air Navigation Order 2016, as amended, the following action required by this Mandatory Permit Directive (MPD) is mandatory for applicable aircraft registered in the United Kingdom operating on a UK CAA Permit to Fly.

Type Approval Holder's Name:			Type/Model Designation(s):		
P&M Aviation Ltd			Various, see b	elow	
Title:	Clevis Pin / Split Ring Installations – Inspection / Replacement				
Manufacturer:	P&M Aviation Ltd				
Applicability:	All Microlights where P & M Aviation Ltd is the Type Approval Holder:				
	TADS No	. Aircraft	Туре	TADS No.	Aircraft Type
	BM2 BM3 BM4 BM5 BM10 BM17 BM14 BM16 BM17 BM23 BM25	Gemini S Tri-Flyer Gemini F Panther 2 Pegasus Pegasus Gemini F Scorcher Pegasus Gemini F Pegasus	print Sprint Iash XL-S XL-R Flash Flash 2 Iash 2 Flash 2 Iash 2 Alpha XL-Q	BM43 BM44 BM45 BM46 BM50 BM51 BM53 BM54 BM56 BM60 BM65	Mainair Mercury Pegasus Quasar 2 TC Cyclone AX3//503 Pegasus Quantum 15 (Rotax 2-stroke engines) Mainair Blade Pegasus Quantum 15-912 Mainair Blade 912 Cyclone AX2000 Mainair Rapier Pegasus Quantum 15-HKS Mainair Blade 912S Flight Design CT2K (rudder control)
	BM27 BM28 BM31 BM33 BM37 BM38 BM42	Chaser S Pegasus Chaser S Chaser S Chaser S Pegasus Pegasus	Photon 1000 508 447 Quasar Quasar – TC	BM66 BM70 BM72 BM77 BM80 BM81 BM83	Pegasus Quik Quik GT450 Flight Design CTSW (rudder control) QuikR Quik GTR PulsR Flight Design CTSL (rudder control)

Reason:	 Following maintenance, a clevis pin came out of the RP-4 roll trim system pulley on a QuikR causing a left turn. The split ring securing the clevis pin had come out. It is not known if the ring was disturbed during the maintenance. The split ring which came out was the same "spiral start" pattern as that which has caused trouble before (see Service Bulletin 139). This pattern of ring has no positive stop, so that simple rotation of the ring (e.g. caused by it getting caught on something) will cause it to disengage. Disengagement of the split ring and subsequent clevis pin departure could affect the control of the aircraft. 				
Effective Date:	24 November 2016				
Compliance/Action:	Compliance is required as follows, unless previously accomplished:				
	 Before further flight, from the effective date of this MPD, inspect all clevis pin / split ring installations on the aircraft in accordance with paragraph 2 of P & M Aviation Ltd Service Bulletin 144. 				
	 If the inspection in paragraph 1 reveals any spiral start pattern split rings they must be replaced in accordance with paragraph 2 of P & M Aviation Ltd Service Bulletin 144 before further flight. 				
	 Record the inspection from paragraph 1 and any necessary rectification action from paragraph 2 in the aircraft technical log in accordance with paragraph 3 of P & M Aviation Ltd Service Bulletin 144. 				
	4. Repeat the actions in paragraphs 1, 2 and 3 at each Permit to Fly revalidation.				
ENSURE COMPLIANCE WITH THIS MPD IS RECORDED IN THE AIRCRAFT LOGBOOK					
Reference Publications:	P & M Aviation Ltd Service Bulletin Number 144, Issue 3, dated 27 October 2016.				
Remarks:	 This MPD was not posted for consultation because of the urgency of the requirement. 				
	 Enquiries regarding this Mandatory Permit Directive should be referred to: GA Unit, Civil Aviation Authority, Safety and Airspace Regulation Group, Aviation House, Gatwick Airport South, West Sussex, RH6 0YR. Tel: +44 (0)1293 573988 E-mail: <u>ga@caa.co.uk</u> 				