

# **OCCURRENCE LISTING**

# Aircraft Below 5700kg OCCURRENCES RECORDED BETWEEN 01 May 2013 and 31 May 2013

# **FIXED WING AIRCRAFT**

AERONCA 7AC	CONTINENTAL (TELEDYNE) USA (A65- 8)	Cruise	Essex	19/05/2013	201305700

Break up of propeller in flight. Safe forced landing carried out.

Pilot observed an irregular shaped object depart upwards and to the left over the cockpit followed by a strong vibration. A/c throttled back to idle and pilot saw that the propeller disc did not look as it should. As a result of the vibration the mags were cut to stop the engine and the pilot looked for a field to land. A/c landed without further damage or any injury.

AVIONS ROBIN DR400	LYCOMING	Unknown	EGKH:	11/03/2013	201302647	
	235 FAMILY		Lashenden/Headcorn			

A/c returned from short flight with burning electrical smell.

On investigation alternator bolts missing and belt on pulley had come away. Alternator had been replaced 77hrs prior to flight but records did not show split pin installation. Task cards updated to check security of split pins at 50hr checks.

AVIONS ROBIN DR400	LYCOMING	Taxi from runwav	EGJB (GCI): Guernsev.	10/05/2013	201305181	
,						
	320 FAMILY		Channel Is.			

A/c struck a sign.

Pilot made an error turning onto taxi line E instead of F. ATC informed the pilot who turned the a/c across an airside road, striking a 'Stop' road sign with the LH wing. A/c shut down and towed to correct apron where it was inspected by an engineer who reported that it was airworthy.

Content:	This list contains occurrences and accidents to aircraft of 5700kg and below recorded on the MOR database during the period shown above. The list includes information reported to the CAA, information from CAA investigations and deductions by CAA staff. The authenticity of the contents or absence of errors and omissions cannot be guaranteed. <b>The list contains preliminary information.</b>
Purpose:	The information is supplied for flight safety purposes only.
Queries & Reporting:	Contact Safety Data Department, Civil Aviation Authority, Aviation House, Gatwick Airport, W Sussex, RH6 0YR. Tel: 01293 573220, Fax: 01293 573972, sdd@caa.co.uk
	YOUR REPORT COULD PREVENT SOMEONE ELSE'S ACCIDENT

**AVIONS ROBIN DR400** UNKNOWN Cruise ORTAC 18/05/2013 201305603 Infringement of the Channel Islands CTR (Class A) by an a/c squawking 1177 at 3000ft. A/c identified via London Info as a Robin DR400. Standard separation maintained. The Robin DR400 called 5nm inside the Channel Island Control Zone, was indentified and vectored West to remain clear of Alderney airspace. **AVIONS ROBIN DR400** LYCOMING EGLC (LCY): London city 18/05/2013 201305615 Cruise 235 FAMILY Infringement of the London City CTA (Class D) by an a/c, identified via Mode S, as a Robin DR400 squawking 7000 at 2000ft resulting in loss of separation with a London City inbound EMB190. CAIT activated. Traffic info given. Information indicates that the infringing a/c was detected by CAIT, the Thames controller took appropriate action and although separation was lost, the a/c were deemed not to be in unsafe proximity. The pilot believes a minor distraction led to this incident however the appropriate lessons appear to have been learnt. **AVIONS ROBIN DR400** LYCOMING En-route EGSC (CBG): Cambridge 19/04/2013 201304162 320 FAMILY Infringement of the Cambridge ATZ (Class G) by a DR400 at 1300ft. Departure cancelled until DR400 vacated. Traffic info given. **AVIONS ROBIN R2120** LYCOMING Cruise EGMC (SEN): Southend 04/02/2013 201301156 235 FAMILY Infringement of the Southend ATZ (Class G) by a R2120U at 2000ft resulting in an inbound A319 being broken from the ILS at 8DME under a DS. Separation minima was maintained Pilot subsequently apologised. BEECH 200 UNKNOWN 28/02/2013 201302078 Cruise En route Prolonged loss of communication (PLOC). A few attempts made to contact the pilot. Eventually contact was made after being radio silent for 20m. BEECH 200 UNKNOWN EGHH (BOH): 23/04/2013 201304362 En-route Bournemouth/Hurn Traffic operating around the positions of a BE200 and a Robin HR200 were not painting on Bournemouth primary radar. Traffic info given. BEECH 200 PRATT & WHITNEY Initial climb EIDW (DUB): Dublin 14/05/2013 201305442 (CANADA) **PT-6 FAMILY** PAN declared and a/c returned when fuel vapour was noticed coming from RH outer fuel filler cap. The a/c had been refuelled prior to departure and on pre-flight visual inspection, all caps had appeared to be secure and locked down. After landing, the filler cap was inspected and it was found that it was sitting at a slight angle although it was fully locked in position. Cap refitted correctly and a/c departed normally. BEECH 200 PRATT & WHITNEY EGBJ (GLO): 27/05/2013 201305977 Level off-(CANADA) touchdown Gloucestershire PT-6 FAMILY Burst tyre on landing

As the a/c touched down, smoke was observed from the LH undercarriage. Pilot was advised and asked if any assistance was needed but this was declined. As the a/c passed North of the tower, more smoke was observed so a ground incident was initiated and RFFS deployed. The a/c stopped on the runway and it was reported that the outer tyre had burst. A/c was able to taxi back to parking area.

Standing : BEECH 200 PRATT & WHITNEY EGSG: Stapleford 18/05/2013 201305991 (CANADA) Engine(s) Not PT-6 FAMILY Operating Discrepancies in fuel calculations. A/c fuel tanks had not been filled in correct sequence. LH fuel quantity indicator unserviceable. BEECH 200 PRATT & WHITNEY Cruise EGSC (CBG): Cambridge 02/05/2013 201304929 (CANADA) PT-6 FAMILY UK AIRPROX 2013/032 - Inbound military a/c received/complied with TCAS RA against a BE200 at 3000ft 8nm West of Cambridge. Traffic info given. BEECH 36 CONTINENTAL EGSH (NWI): Norwich Initial climb 10/04/2013 201304726 (TELEDYNE) USA 520 FAMILY Green laser attack BEECH 76 UNKNOWN EGJA (ACI): 02/02/2013 201301149 En-route Alderney, Channel Is. A BE76 was instructed after go-around to climb to 2000ft. Following the go-around the a/c climbed to 3000ft. Separation minima was maintained. BEECH 90 UNKNOWN 28/03/2013 201303249 Climb to cruising En route level or altitude A/c returned due to Mode C discrepancy. ATC had given clearance to FL230 but a/c (BE90) was indicating FL246, pilot's view was indicated as maintaining FL230. Controller stopped B757 at FL260 and turned onto hdg180. Pilot made the decision to return after trying box 2 which also did not work. BEECH 90 UNKNOWN En-route EGLC (LCY): London city 30/04/2013 201304707 Infringement of the London City CTR (Class D) by a BE90 resulting in a loss of separation against an outbound RJ85. Traffic info and avoiding action given. Pilot error acknowledged. BEECH G58 CONTINENTAL UNKNOWN EGHO : Thruxton 25/04/2013 201304714 (TELEDYNE) USA 520 FAMILY UK AIRPROX 2013/023 - Military helicopter and a BE58 at 2500ft North of Thruxton. **BRITTEN NORMAN BN2** LYCOMING 26/04/2013 EGPA (KOI): Kirkwall 201304462 Taxi from runway 540 FAMILY Runway incursion. BN2P failed to report final R/W14 as instructed and was observed to be taxing through R4 onto main apron. At the time the controller had been occupied with a telephone call amending release of another a/c and updating service status of DME. On looking up had noticed that the a/c had landed. Pilot was informed that he had not received a landing clearance. No other traffic on frequency or on the manoeuvring area. BRITTEN NORMAN BN2A LYCOMING Taxiing to/from EGPA (KOI): Kirkwall 07/05/2013 201304972 540 FAMILY runway

BN2P cleared to taxi hold point R4 travelled past clearance limit and was observed taxing to holding point R1 adjacent to main runway. Pilot was reminded of his

At the time an AS355 had been cleared to land R/W09 and was within 4nm. Pilot apologised and held at R1. Pilot distraction cited as a causal factor.

clearance and R1 stopbar was switched on. Pilot apologised.

CESSNA 150	CONTINENTAL (TELEDYNE) USA 200 FAMILY	Cruise	Donna Nook	03/04/2013	201303482
the range at the time of the in Humberside radar informed pilot to contact Donna Nook.	nted active Danger Area EG D307 (D nfringement. Donna Nook that the infringer had la Pilot subsequently contacted Donna on frequency if pilot intended to com	nded at Strubby airfield. Do a Nook ATC and allegedly	onna Nook contacted Strubby a	airfield, who confirme	ed a/c's identity and asked
CESSNA 150	CONTINENTAL (TELEDYNE) USA 200 FAMILY	Final approach	EGCW : Montgomeryshire/Welshpo ol	07/05/2013	201305673
UK Reportable Accident. A/o	struck some fence posts during cro	sswind landing. Two POB i	no injuries. Subject to AAIB AAF	RF investigation.	
CESSNA 152	LYCOMING 235 FAMILY	Unknown	EGNH (BLK): Blackpool	13/03/2013	201302674
	gency declared. A/c landed safely. had stopped just before landing.				
CESSNA 152	LYCOMING 235 FAMILY	Cruise	Aylesbury	01/04/2013	201303384
PAN declared due to rough r ATC ascertained the a/c's po kept informed. A/c landed sa	osition and gave information of the ne	earest airfields. Pilot electe	d to continue his return to depar	rture airfield. D&D aı	nd other relevant parties
CESSNA 152	LYCOMING 235 FAMILY	Climb to cruising level or altitude	EGMT: Thurrock	28/03/2013	201303468
The flight was a routine train the a/c towards landing site a	ugh running engine. A/c diverted. ing sortie. Standard touch drills were and instructor gave instructions to go ngine with significantly reduced perfo ling was carried out.	o-around. Full power was a	pplied and climb commenced. T	his was accompanie	ed by a loud high pitched
CESSNA 152	LYCOMING 235 FAMILY	Circuit pattern - downwind	EGNV (MME): TEESSIDE	06/04/2013	201303605
	ouch-and-go clearance, the a/c displa g clearance and D&D informed. The				
CESSNA 152	LYCOMING 235 FAMILY	Taxi	EGBP : KEMBLE	26/04/2013	201304473
	outside Hangar 2 with the tow bar sti e incident and of the possible likeliho			pushed back in front	t of Hangar 2.
OFOCNIA 450	LYGOMING	T. P.	FOTE F	00/05/00/5	004004000

Landing

Runway infringement. Reporter alleged that a solo student flying a C152 landed on R/W24 before the preceding a/c had vacated the runway. Reporter stated that the solo student had been informed twice, when on short final, that the runway was occupied.

EGTF : Fairoaks

03/05/2013

201304809

CESSNA 152

LYCOMING

235 FAMILY

	LYCOMING 235 FAMILY	Cruise	EGMC (SEN): Southend	23/04/2013	201304842
Green laser attack.					
CESSNA 152	UNKNOWN	Approach	EGNX (EMA): NOTTINGHAM EAST MIDLANDS	01/05/2013	201305338
Green laser attack.					
CESSNA 172	LYCOMING 360 FAMILY	En-route	EGSC (CBG): Cambridge	07/03/2013	201302392
· · · · · · · · · · · · · · · · · · ·	mary flight display and navigationa and a/c returned to fly a procedura	•			
CESSNA 172	LYCOMING 235 FAMILY	En-route	EGFF (CWL): Cardiff	31/03/2013	201303317
pilot admitted that the transp	11:08 and departed at 12:05. On be onder was 'ancient' and it is likely to	that it is not Mode S compatil		e radar display alo	ngside the SSR label. Th
	LYCOMING 320 FAMILY or pressure when requested to exp	Taxi from runway edite clearance of R/W20, du	, ,		
bursting when braking heavil		edite clearance of R/W20, du	le to a following helicopter on ap	proach, resulting in	
C172 pilot allegedly felt unde bursting when braking heavil	320 FAMILY or pressure when requested to exp y after using excessive speed to tu	edite clearance of R/W20, du	le to a following helicopter on ap	proach, resulting in	
C172 pilot allegedly felt under bursting when braking heavil C172 was pushed clear of RACESSNA 172	320 FAMILY er pressure when requested to exp y after using excessive speed to tu W20 and Taxiway E. No reported  LYCOMING	edite clearance of R/W20, durn off the runway. injuries. No damage to C172  Unknown  ng 7010 with Mode C 3100ft.	other than the burst tyre and tub	peroach, resulting in be. 12/05/2013	C172's LH tyre and tube
C172 pilot allegedly felt under bursting when braking heavil C172 was pushed clear of Rocessna 172  Infringement of the London T The CFI of the flying club has	320 FAMILY or pressure when requested to exp y after using excessive speed to tu W20 and Taxiway E. No reported  LYCOMING 320 FAMILY  TMA (Class A) by a C172 squawkin	edite clearance of R/W20, durn off the runway. injuries. No damage to C172  Unknown  ng 7010 with Mode C 3100ft.	other than the burst tyre and tub	peroach, resulting in be. 12/05/2013	C172's LH tyre and tube
C172 pilot allegedly felt under bursting when braking heavil C172 was pushed clear of RACESSNA 172  Infringement of the London The CFI of the flying club has CESSNA 172  Infringement of the LTMA (C	ar pressure when requested to exp y after using excessive speed to tu. W20 and Taxiway E. No reported  LYCOMING 320 FAMILY  TMA (Class A) by a C172 squawkir is been alerted and has taken appro-	edite clearance of R/W20, durn off the runway. injuries. No damage to C172  Unknown  ng 7010 with Mode C 3100ft. opriate action.  Cruise  ass D) by a C172 at 3000ft. E	other than the burst tyre and tub  Overhead Thurrock  Standard separation maintained.  EGKK (LGW): London/Gatwick	12/05/2013 26/05/2013	201305959
C172 pilot allegedly felt under bursting when braking heavil C172 was pushed clear of RACESSNA 172  Infringement of the London The CFI of the flying club has CESSNA 172  Infringement of the LTMA (C	ar pressure when requested to exp y after using excessive speed to tu W20 and Taxiway E. No reported  LYCOMING 320 FAMILY  TMA (Class A) by a C172 squawkir is been alerted and has taken appropriately a property of the company of th	edite clearance of R/W20, durn off the runway. injuries. No damage to C172  Unknown  ng 7010 with Mode C 3100ft. opriate action.  Cruise  ass D) by a C172 at 3000ft. E	other than the burst tyre and tub  Overhead Thurrock  Standard separation maintained.  EGKK (LGW): London/Gatwick	12/05/2013 26/05/2013	201305959
C172 pilot allegedly felt under bursting when braking heavil C172 was pushed clear of RACESSNA 172  Infringement of the London The CFI of the flying club has CESSNA 172  Infringement of the LTMA (CAppropriate CAA action bein CESSNA 172  C172 flew through Hinton Driclear of the zone.	ar pressure when requested to exp y after using excessive speed to tu W20 and Taxiway E. No reported  LYCOMING 320 FAMILY  TMA (Class A) by a C172 squawkir is been alerted and has taken appropriate and present the second property of the second property	edite clearance of R/W20, durn off the runway. injuries. No damage to C172  Unknown  ng 7010 with Mode C 3100ft. opriate action.  Cruise  En-route  En-route	other than the burst tyre and tub  Overhead Thurrock  Standard separation maintained.  EGKK (LGW): London/Gatwick  Blind calls made without success.  Hinton Drop Zone  's presence and alerted para dro	26/05/2013  Standard separati  02/02/2013  p a/c. Para drop su	201305269  201305959  ion maintained.  201301184  uspended until C172 was
C172 pilot allegedly felt under bursting when braking heavil C172 was pushed clear of RACESSNA 172  Infringement of the London Table CFI of the flying club has CESSNA 172  Infringement of the LTMA (CAppropriate CAA action bein CESSNA 172  C172 flew through Hinton Driclear of the zone.	ar pressure when requested to exp y after using excessive speed to tu. W20 and Taxiway E. No reported  LYCOMING 320 FAMILY  TMA (Class A) by a C172 squawkir is been alerted and has taken appropriately a present the company of the c	edite clearance of R/W20, durn off the runway. injuries. No damage to C172  Unknown  ng 7010 with Mode C 3100ft. opriate action.  Cruise  En-route  En-route	other than the burst tyre and tub  Overhead Thurrock  Standard separation maintained.  EGKK (LGW): London/Gatwick  Blind calls made without success.  Hinton Drop Zone  's presence and alerted para dro	26/05/2013  Standard separati  02/02/2013  p a/c. Para drop su	201305269  201305959  ion maintained.  201301184  uspended until C172 was
C172 pilot allegedly felt under bursting when braking heavil C172 was pushed clear of RACESSNA 172  Infringement of the London The CFI of the flying club has CESSNA 172  Infringement of the LTMA (CAPPROPRIATE CAPA action bein CESSNA 172  C172 flew through Hinton Draclear of the zone. First para drop had taken pla CESSNA 206	ar pressure when requested to exp y after using excessive speed to to W20 and Taxiway E. No reported  LYCOMING 320 FAMILY  TMA (Class A) by a C172 squawkir s been alerted and has taken appro  LYCOMING 360 FAMILY  lass A) and Gatwick CTA/CTR (Cla g taken as a result of this incident.  LYCOMING 320 FAMILY  op Zone whilst active. DZ controlled the at 5000ft. Para drop a/c then class.	edite clearance of R/W20, durn off the runway. injuries. No damage to C172  Unknown  Ing 7010 with Mode C 3100ft. opriate action.  Cruise  En-route  En-route  In became aware of the C172  imbed to FL130 for the second Approach	other than the burst tyre and tube Overhead Thurrock Standard separation maintained.  EGKK (LGW): London/Gatwick Slind calls made without success.  Hinton Drop Zone 's presence and alerted para droud drop at which point the C172 of EGPF (GLA): Glasgow	26/05/2013  Standard separati  02/02/2013  p a/c. Para drop suwas observed over	201305269  201305959  ion maintained.  201301184  uspended until C172 was head the zone.

Infringer reached FL116 before tracking Westbound towards the Salisbury Plain Danger Area, where it eventually climbed to FL140. TC reporter stated that the a/c infringed the active airspace for 5mins during a busy and complex Wx afflicted session on SW Deps. Solent Radar had attempted to contact the infringer without success. TC spoke to D&D cell who established the infringer to be a C208 in 2-way communication with Netheravon. On instruction of D&D, Netheravon agreed to speak to C208 on landing regarding active times for Airway Q41.

Infringement of Airway P18 (Class D) by a C402 in cruise at P1.90. Reporter commended on the clarity of the chart in use and the subsequent misinterpretation of airspace.  CESSNA 421 UNKNOWN En-route EGCN: DONCASTER 09/03/2013 201302 SHEFFIELD  PAN declared and air diverted due rough running engine.  CESSNA 421 CONTINENTAL Scheduled EGTC: Cranfield 04/03/2013 201302 CESSNA 421 CONTINENTAL Scheduled EGTC: Cranfield 04/03/2013 201302 S20 FAMILY  Excessive corrosion found on mainplanes. On removal of the outboard de-icing boots on both wings, the leading edges were found to be excessively corroded. Thorough inspections recommended at maintenance input.(The mainplane leading edge forms the forward face of the wing fluid tank).  CESSNA 510 PRATT & WHITNEY Taxl from runway (CANADA) Other  After landing on RW05, C510 subsequently taxled along Taxiway Y without further ATC clearance. C510 acknowledged their mistake and apologised. C510 plot commented that during the landing roll. ATC had asked them to expedite vacating the runway which was an extra pressure and may have been feator. Information indicates that a single engine grass strip runs adjacent to RW05 and crews need to be aware of receiving clearance down either Taxley.  CESSNA 510 PRATT & WHITNEY Climb to crusing En route 12/04/2013 201302  CESSNA 510 UNKNOWN Normal descent EGGW (LTN): 17/04/2013 201302  CESSNA 510 UNKNOWN Normal descent EGGW (LTN): 17/04/2013 201302  CESSNA 510 UNKNOWN Normal descent EGGW (LTN): 17/04/2013 201302  CESSNA 510 PRATT & WHITNEY Intermediate LEGGW (LTN): 17/04/2013 201302  CESSNA 510 PRATT & WHITNEY Intermediate LEGGW (LTN): 17/04/2013 201302  CESSNA 510 PRATT & WHITNEY Intermediate LEGGW (LTN): 17/04/2013 201302  CESSNA 510 PRATT & WHITNEY Intermediate LEGGW (LTN): 17/04/2013 201302  CESSNA 510 PRATT & WHITNEY Intermediate LEGGW (LTN): 17/04/2013 201302  CESSNA 510 PRATT & WHITNEY Intermediate LEGGW (LTN): 17/04/2013 201302  CESSNA 510 PRATT & WHITNEY Intermediate LEGGW (LTN): 17/04/2013 201302		CONTINENTAL (TELEDYNE) USA 520 FAMILY	En-route	EGNR : Hawarden	03/05/2013	201304848
ITELEDYNE) USA 520 FAMILY  Infringement of Airway P18 (Class D) by a C402 in cruise at FL90.  Reporter commented on the clarity of the chart in use and the subsequent misinterpretation of airspace.  DESSNA 421 UNKNOWN En-route EGCN: DONCASTER 09/03/2013 201302 SHEFFIELD  PAN declared and a/c diverted due rough running engine.  DESSNA 421 CONTINENTAL Scheduled (TELEDYNE) USA maintenance 520 FAMILY  Excessive corrosion found on mainplanes.  Din removal of the outboard devicing boots on both wings, the leading edges were found to be excessively corroded. Thorough inspections recommended a maintenance input (The mainplane leading edge forms the forward face of the wing fuel tank).  DESSNA 510 PRATT & WHITNEY Taxl from runway LSGG (GVA): 06/04/2013 201303 (CANADA) Other  After landing on RW05, C510 subsequently taxled along Taxlway? Without further ATC clearance. C510 acknowledged their mistake and applogised. C510 pilot commented that during the landing roll. ATC had asked them to expedite vacating the runway which was an extra pressure and may have been actor. Information indicates that a single engine grass strip runs adjacent to R/W05 and crews need to be aware of receiving clearance down either Taxlwa CESSNA 510 Was cleared to FL90 but seen to climb to FL96. The controller queried the pilot over his pressure setting, local programs of the pilot confirmed that the a/c remained inadvertently on the local QNH.  DESSNA 510 UNKNOWN Normal descent EGW (LTN): 17/04/2013 201303 (CANADA) Other EGSSNA 510 UNKNOWN Normal descent EGW (LTN): 17/04/2013 201303 (CANADA) Other EGSSNA 510 Was cleared to FL90 but seen to climb to FL96. The controller queried the pilot over his pressure setting, local programs and the pilot confirmed that the a/c remained inadvertently on the local QNH.  DESSNA 510 UNKNOWN Normal descent EGW (LTN): 17/04/2013 201303 (CANADA) Other EGSSNA 510 UNKNOWN Normal descent EGW (LTN): 17/04/2013 201303 (CANADA) Other EGSSNA 510 UNKNOWN Normal descent EGW (LTN): 17/04/2013 201303 (CANADA) Other EGSSNA 510 U	=		-	•		
CESSNA 421 UNKNOWN En-route EGCN : DONCASTER 09/03/2013 201302 SHEFFIELD  PAN declared and a/c diverted due rough running engine.  CESSNA 421 CONTINENTAL (TELEDYNE) USA maintenance EGTC : Cranfield 04/03/2013 201302 520 FAMILY  Excessive corrosion found on mainplanes.  On removal of the outboard de-icing boots on both wings, the leading edges were found to be excessively corroded. Thorough inspections recommended a maintenance input. (The mainplane leading edge forms the forward face of the wing fuel tank).  CESSNA 510 PRATT & WHITNEY (CANADA) Other  After landing on RW05, C510 subsequently taxied along Taxiway Y without further ATC clearance. C510 acknowledged their mistake and apologised. C510 pilot commented that during the landing roll, ATC had asked them to expedite vacating the runway which was an extra pressure and may have been factor. Information indicates that a single engine grass strip runs adjacent to RW05 and crews need to be aware of receiving clearance down either Taxiw.  CESSNA 510 PRATT & WHITNEY Climb to cruising level or altitude Other  CESSNA 510 UNKNOWN Normal descent EGGW (LTN): 17/04/2013 201303 (CANADA) Intelligence of the pilot over his pressure setting, local progress of the pilot confirmed that the a/c remained inadvertently on the local ONH.  CESSNA 510 UNKNOWN Normal descent EGGW (LTN): 17/04/2013 201303 (CANADA) Other  CESSNA 510 PRATT & WHITNEY Intermediate LFPB (LBG): Paris Le 24/04/2013 201303 (CANADA) Other  CESSNA 510 PRATT & WHITNEY Intermediate LFPB (LBG): Paris Le 24/04/2013 201303 (CANADA) Other	CESSNA 402	(TELEDYNE) USA	Cruise	TILNI	25/05/2013	201305962
PAN declared and a/c diverted due rough running engine.  CESSNA 421  CONTINENTAL TELEDYNE) USA maintenance  Excessive corresion found on mainplanes.  PRATT & WHITNEY Taxi from runway LSGG (GVA): 06/04/2013 20130: 06/04/2013 2013	- · · · · · · · · · · · · · · · · · · ·		equent misinterpretation	of airspace.		
CESSNA 421  CONTINENTAL (TELEDVNE) USA maintenance  Excessive corrosion found on mainplanes.  Excessive corrosion found on mainplanes.  On removal of the outboard de-icing boots on both wings, the leading edges were found to be excessively corroded. Thorough inspections recommended a maintenance input. (The mainplane leading edge forms the forward face of the wing fuel tank).  CESSNA 510  PRATT & WHITNEY (CANADA)	CESSNA 421	UNKNOWN	En-route		09/03/2013	201302682
(TELEDYNE) USA 520 FAMILY  maintenance Sexcessive corrosion found on mainplanes.  On removal of the outboard de-icing boots on both wings, the leading edges were found to be excessively corroded. Thorough inspections recommended a maintenance input. (The mainplane leading edge forms the forward face of the wing fuel tank).  CESSNA 510  PRATT & WHITNEY (CANADA)	PAN declared and a/c diverted d	lue rough running engine.				
On removal of the outboard de-icing boots on both wings, the leading edges were found to be excessively corroded. Thorough inspections recommended a maintenance input. (The mainplane leading edge forms the forward face of the wing fuel tank).  CESSNA 510  PRATT & WHITNEY (CANADA) Other  After landing on R/W05, C510 subsequently taxied along Taxiway Y without further ATC clearance. C510 acknowledged their mistake and apologised. C510 pilot commented that during the landing roll, ATC had asked them to expedite vacating the runway which was an extra pressure and may have been factor. Information indicates that a single engine grass strip runs adjacent to R/W05 and crews need to be aware of receiving clearance down either Taxiwa certains.  CESSNA 510  PRATT & WHITNEY Climb to cruising level or altitude  CESSNA 510  PRATT & WHITNEY Climb to cruising level or altitude  CESSNA 510  UNKNOWN  Normal descent EGGW (LTN): 17/04/2013 201304  CESSNA 510  UNKNOWN  Normal descent EGGW (LTN): 17/04/2013 201304  CESSNA 510  PRATT & WHITNEY Intermediate LFPB (LBG): Paris Le 24/04/2013 201304  CESSNA 510  PRATT & WHITNEY Intermediate LFPB (LBG): Paris Le 24/04/2013 201304  CESSNA 510  PRATT & WHITNEY Intermediate Bourget  CESSNA 510  PRATT & WHITNEY Intermediate Approach Bourget	CESSNA 421	(TELEDYNE) USA		EGTC : Cranfield	04/03/2013	201302237
After landing on R/W05, C510 subsequently taxied along Taxiway Y without further ATC clearance. C510 acknowledged their mistake and apologised. C510 pilot commented that during the landing roll, ATC had asked them to expedite vacating the runway which was an extra pressure and may have been factor. Information indicates that a single engine grass strip runs adjacent to R/W05 and crews need to be aware of receiving clearance down either Taxiwa.  CESSNA 510  PRATT & WHITNEY Climb to cruising In route 12/04/2013 201303 (CANADA) Other  Prailure to change pressure to SPS. C510 was cleared to FL90 but seen to climb to FL96. The controller queried the pilot over his pressure setting, local pre 1996mb.  The pilot confirmed that the a/c remained inadvertently on the local QNH.  CESSNA 510  UNKNOWN  Normal descent EGGW (LTN): London/Luton  Tr/04/2013 201304  Green laser attack.  CESSNA 510  PRATT & WHITNEY (CANADA) Other  Intermediate LFPB (LBG): Paris Le 24/04/2013 201305 LONGON Bourget  Advance CS10 acknowledged their mistake and apologised.  CESSNA 510  PRATT & WHITNEY (CANADA) Other  Other	On removal of the outboard de-id	cing boots on both wings, the leadi		•	ough inspections reco	ommended at next
CESSNA 510  PRATT & WHITNEY Climb to cruising level or altitude Other  CESSNA 510  UNKNOWN  Normal descent  EGGW (LTN): London/Luton  PRATT & WHITNEY CESSNA 510  UNKNOWN  Normal descent  EGGW (LTN): London/Luton  PRATT & WHITNEY CESSNA 510  UNKNOWN  Normal descent  EGGW (LTN): London/Luton  PRATT & WHITNEY CESSNA 510  UNKNOWN  Normal descent  EGGW (LTN): London/Luton  PRATT & WHITNEY CESSNA 510  UNKNOWN  Normal descent  EGGW (LTN): London/Luton  PRATT & WHITNEY CESSNA 510  UNKNOWN  Normal descent  EGGW (LTN): London/Luton  PRATT & WHITNEY London/Luton  PRATT & WHITNEY London/Luton  PRATT & WHITNEY CESSNA 510  P	CESSNA 510		Taxi from runway		06/04/2013	201303645
(CANADA) level or altitude Other  Failure to change pressure to SPS. C510 was cleared to FL90 but seen to climb to FL96. The controller queried the pilot over his pressure setting, local presents. The pilot confirmed that the a/c remained inadvertently on the local QNH.  CESSNA 510 UNKNOWN Normal descent EGGW (LTN): 17/04/2013 201304 London/Luton  Green laser attack.  CESSNA 510 PRATT & WHITNEY Intermediate LFPB (LBG): Paris Le 24/04/2013 201305 (CANADA) approach Bourget				Geneve/Commin		
PRATT & WHITNEY Intermediate (CANADA) Other    Septemble   Canada   Canada	C510 pilot commented that durin	Other  ubsequently taxied along Taxiway of the landing roll, ATC had asked	them to expedite vacating	arance. C510 acknowledged th g the runway which was an ext	ra pressure and may	have been a contribu
CESSNA 510  PRATT & WHITNEY Intermediate LFPB (LBG): Paris Le 24/04/2013 201305 (CANADA) approach Bourget Other	C510 pilot commented that durin factor. Information indicates that	Other  ubsequently taxied along Taxiway of the landing roll, ATC had asked a single engine grass strip runs action of the present the strip runs action of the present the pre	them to expedite vacating ljacent to R/W05 and cred	arance. C510 acknowledged the tunway which was an exture was need to be aware of receiving the control of the c	ra pressure and maying clearance down e	have been a contribu
CESSNA 510 PRATT & WHITNEY Intermediate LFPB (LBG): Paris Le 24/04/2013 201305 (CANADA) approach Bourget Other	C510 pilot commented that durin factor. Information indicates that  CESSNA 510  Failure to change pressure to SF 996mb.	Other  ubsequently taxied along Taxiway of the landing roll, ATC had asked a single engine grass strip runs action of the	them to expedite vacating ljacent to R/W05 and cressing level or altitude	arance. C510 acknowledged the runway which was an extension was need to be aware of receiving the route	ra pressure and may ng clearance down e 12/04/2013	have been a contributither Taxiways Y or Z
(CANADA) approach Bourget Other	C510 pilot commented that durin factor. Information indicates that  CESSNA 510  Failure to change pressure to SF 996mb.  The pilot confirmed that the a/c r	Other  Subsequently taxied along Taxiway of the landing roll, ATC had asked a single engine grass strip runs action as the subsequently of the landing roll, ATC had asked a single engine grass strip runs action as the landing roll, and the la	them to expedite vacating ljacent to R/W05 and crescipled and cres	arance. C510 acknowledged the grance of the runway which was an exture was need to be aware of received a route.  En route  the controller queried the pilot of the controller queried the controller	ra pressure and may ng clearance down e  12/04/2013  ver his pressure setti	have been a contributither Taxiways Y or Z
Other	C510 pilot commented that durin factor. Information indicates that  CESSNA 510  Failure to change pressure to SF996mb. The pilot confirmed that the a/c r  CESSNA 510	Other  Subsequently taxied along Taxiway of the landing roll, ATC had asked a single engine grass strip runs action as the subsequently of the landing roll, ATC had asked a single engine grass strip runs action as the landing roll, and the la	them to expedite vacating ljacent to R/W05 and crescipled and cres	arance. C510 acknowledged the grance of the runway which was an exture was need to be aware of received a route.  En route  the controller queried the pilot of the controller queried the controller	ra pressure and may ng clearance down e  12/04/2013  ver his pressure setti	have been a contribution of the contribution o
Green laser attack. Pilot struck in the left eye causing temporary blindness and irritation.	C510 pilot commented that durin factor. Information indicates that  CESSNA 510  Failure to change pressure to SF 996mb. The pilot confirmed that the a/c r  CESSNA 510  Green laser attack.	Other  ubsequently taxied along Taxiway of the landing roll, ATC had asked a single engine grass strip runs action of the	them to expedite vacating ljacent to R/W05 and crestljacent to R/W05 and crestljacent to R/W05 and crestljacent or altitude seen to climb to FL96. The QNH.	arance. C510 acknowledged to get the runway which was an exture was need to be aware of received and the route the controller queried the pilot of the controller queried the pilot of the condon/Luton	ra pressure and maying clearance down ender a second control of the second control of th	have been a contribution of the contribution o
	C510 pilot commented that durin factor. Information indicates that  CESSNA 510  Failure to change pressure to SF 996mb. The pilot confirmed that the a/c r  CESSNA 510  Green laser attack.	Other  Ubsequently taxied along Taxiway on the landing roll, ATC had asked a single engine grass strip runs acceptable asked a single engine grass strip runs acceptable (CANADA)  Other  PS. C510 was cleared to FL90 but seemained inadvertently on the local UNKNOWN  PRATT & WHITNEY (CANADA)	them to expedite vacating ljacent to R/W05 and crestljacent to R/W05 and crestljacent to R/W05 and crestljacent or altitude seen to climb to FL96. The QNH.  Normal descent	arance. C510 acknowledged to get the runway which was an ext ws need to be aware of received as a controller queried the pilot of the controller queried the c	ra pressure and maying clearance down ender a second control of the second control of th	have been a contribution of the contribution o
CESSNA 525 WILLIAMS Climb to cruising EGJJ (JER): Jersey, 13/02/2013 201301 FJ44 level or altitude Channel Is.	C510 pilot commented that durin factor. Information indicates that  CESSNA 510  Failure to change pressure to SF 996mb. The pilot confirmed that the a/c r  CESSNA 510  Green laser attack.	Other  Ubsequently taxied along Taxiway of the landing roll, ATC had asked a single engine grass strip runs acceptable asked a single engine grass strip runs acceptable (CANADA)  Other  PS. C510 was cleared to FL90 but seemained inadvertently on the local UNKNOWN  PRATT & WHITNEY (CANADA)  Other  OTHER OTHER OF TAXION OF TAXION OTHER	them to expedite vacating lipacent to R/W05 and cressing level or altitude seen to climb to FL96. The QNH.  Normal descent  Intermediate approach	arance. C510 acknowledged to get the runway which was an ext ws need to be aware of received as a controller queried the pilot of the controller queried the c	ra pressure and maying clearance down ender a second control of the second control of th	have been a contribution of the contribution o

CESSNA F172 CONTINENTAL En-route EGSS (STN): 22/04/2013 201304373 (TELEDYNE) USA London/Stansted 300 FAMILY Infringement of the Stansted CTA (Class D) by a C172 with Mode C indicating 2000ft. CAIT activated. Traffic info given. Various a/c delayed as a result. Standard separation maintained. . A/c observed descending to leave CAS and turned away from South West track. **CESSNA F172** LYCOMING EGPG : Cumbernauld 20/04/2013 201304166 En-route 320 FAMILY A C172 infringed the Glasgow CTA (Class D) at 3500ft. After being informed the base of CAS was 3000ft, the pilot descended. There was no other a/c in the area at the time. The pilot later phoned in and apologised. CESSNA FA152 LYCOMING EGLL (LHR): 07/05/2013 201304983 En-route 235 FAMILY London/Heathrow Infringement of the LTMA (Class A) by a C152 at 2800ft. Avoiding action given. Separation minima was maintained. The student in question has been briefed by his CFI on what he did and the dangers/legality. It has been decided that he will repeat the same navigation route with his instructor, he will then fly with the CFI or deputy CFI on another navigation route involving the coordination of other, unfamiliar controlled airspace. Only when he has demonstrated to the CFI/DCFI to above a satisfactory standard will he then be sent to fly solo again. **CESSNA R182** LYCOMING EGBB (BHX): Birmingham 03/05/2013 201304922 En-route 540 FAMILY Alleged infringement of the Birmingham CTA (Class D) by a C182 at 2800ft. Separation minima was maintained. The pilot was adamant he did not infringe the airspace, believing it was a 'Likely transponder malfunction" **CIRRUS SR22** CONTINENTAL 13/03/2013 201302621 Danger Area (EGD406) En-route (TELEDYNE) USA 550 FAMILY An SR22 infringed Danger Area (EGD406) at 3000ft whilst the range was notified as active. No other a/c were affected by the infringement. **CIRRUS SR22** CONTINENTAL En-route EGHI (SOU): Southampton 28/04/2013 201304491 (TELEDYNE) USA 550 FAMILY Infringement of the Solent CTA (Class D) by an SR22 at 2400ft squawking 7000. Blind calls made without success. Standard separation maintained. **CYCLONE AIRSPORTS PEGASUS** BOMBARDIER ROTAX Northiam 26/05/2013 201306060 Landing roll - on QUANTUM15 runway UK Reportable Accident: On landing, a gust of wind caught the right wing, flipping the a/c over into a fence. One POB with minor injuries. A/c substantially damaged. Subject to AAIB AARF investigation. **DE HAVILLAND DH82** DE HAVILLAND Level off-Hampstead Norreys 07/04/2013 201303787 **GIPSY MAJOR** touchdown UK Reportable Accident: A/c was caught by a gust of wind, ran off runway and came to rest in a field. One POB, no injuries. Subject to AAIB AARF investigation. **DE HAVILLAND DH82** EGKA (ESH): Shoreham 201304652 BRISTOL Cruise 28/04/2013 **GIPSY MAJOR** 

Radio failure during flight. A/c landed safely.

This was the second time in seven days that this a/c had suffered radio failure.

**DE HAVILLAND DH82** BRISTOL Initial climb Dinnington 26/05/2013 201305989 **GIPSY MAJOR** A/c suffered engine failure in climb at 1200ft. MAYDAY declared and a/c made forced landing in field. No reported injuries to the two POB. DE HAVILLAND DHC6 PRATT & WHITNEY EGEC (CAL): 03/05/2013 201304904 Standing (CANADA) Campbeltown **PT-6 FAMILY** External fuel leak, fluctuating readings from aft fuel gauge. Aft fuel gauge started fluctuating readings on arrival. Manual dip carried out and forward tank dipped at 400lbs and aft tank dipped at just over 200lbs. Unable to identify if there was a leak due to having flown through rain showers although there was a strong smell of fuel along the belly panels. Tech Log entry from previous flight had indicated a strong fuel smell identified by a passenger but engineering could not find a fault so a/c was returned to service. Fuel leaks have been logged from the aft tank over the past few days. When a/c was moved for overnight parking the aft gauge now indicated 75lbs of fuel. Tech Log entry made and a/c under investigation. DE HAVILLAND DHC8 PRATT & WHITNEY REVTU Cruise 06/02/2013 201301286 (CANADA) **PW100 FAMILY** Foreign AIRPROX - DHC8 in cruise at FL240 received/complied with TCAS RA to descend and monitor V/S against a/c above, believed a Cessna Citation, in descent travelling right to left. Cessna Citation received/complied with TCAS RA climb. ATC informed. Reporter commented that the a/c came within 500ft of each other and that the DHC8 only made visual contact when the Cessna Citation was above and slightly forward of them. Reporter stated they believed the Cessna Citation had been cleared to descend by ATC. Subject to investigation by the DGAC. **DIAMOND DA20 BOMBARDIER ROTAX** Climb to cruising EGKK (LGW): 23/04/2013 201304370 level or altitude London/Gatwick Infringement of the Gatwick CTR (Class D) by a DA20 squawking 3767 climbing to 2000ft. Separation lost with inbound A319. Traffic info and avoiding action given. DIAMOND DA40 THIELERT 20/04/2013 Approach EGBE (CVT): Coventry 201304671 Centurion 1.7 (TAE 125) DA40 instructed to go-around due runway occupied by PA28 failed to comply and instead continued the 'touch and go'. A/c was piloted by a solo student undertaking circuits. Earlier taxi instruction to a holding point had not been complied with and on previous circuits a/c had bounced along the runway a number of times at estimated height of 4ft. CFI has been notified. DIAMOND DA40 THIELERT EGHI (SOU): Southampton 201304317 En-route 23/04/2013 Centurion 1.7 (TAE 125) Infringement of the Southampton CTA (Class D) by a DA40 at 3000ft led to a loss of separation against an EMB190 outbound from Southampton. DA40 pilot on being passed from Bournemouth had been told to remain outside of CAS. DA40 was put on a heading of 360 to turn it away from the outbound. ERJ190 was put on a heading of 010 and climbed to FL70. DIAMOND DA42 THIELERT Approach EGBJ (GLO): 01/03/2013 201302140 Centurion 1.7 (TAE Gloucestershire 125) PAN declared due to low fuel warning. A/c landed without further incident. Emergency services attended. DIAMOND DA42 UNKNOWN EGNE : Repton/Gamston 20/03/2013 201302904 En-route PAN declared due to undercarriage malfunction. A/c landed safely.

DIAMOND DA42 UNKNOWN Initial climb EGNE: Repton/Gamston 20/03/2013 201303545 PAN declared and a/c diverted due to unsafe LH main gear indication. Pilot requested diversion due to no green undercarriage lights then declared that he would be shutting down LH engine on approach. A/c landed safely with emergency services in attendance. **DIAMOND DA42** OTHER (AUSTRO E4 EICK (ORK): Cork 12/04/2013 201303978 Circuit pattern -(AE300)) base leg DA42 at 1500ft, was calibrating the ILS of R/W35, when the flight crew observed the presence of a powered model a/c on the approach path, in close proximity to the Reporter commented that the DA42 was positioning to fly at 1000ft AGL on the runway centre line at 12DME, which was much lower than approaching a/c would normally be flying. DIAMOND DA42 OTHER (AUSTRO E4 Scheduled EGNE : Repton/Gamston 08/03/2013 201302412 (AE300)) maintenance Insufficient control clearance was found between a bolt in the rudder system and the nose wheel steering mechanism during a post-inspection rebuild. A minimum clearance of 2mm is required but the clearance found was 0.8mm. Inspection showed an incorrect part number for the bolt fitted. The system has not been disturbed since manufacture so it is believed that this has been the situation since a/c build. (The minimum clearance is specified by MSB-42NG-016/1 which is N/A to this airframe by serial number). When the correct size bolt was fitted however, sufficient clearance was obtained. Manufacturer advised. **EUROPA EUROPA BOMBARDIER ROTAX** Cruise EGHI (SOU): Southampton 04/05/2013 201304879 912 Infringement of the Solent CTA (Class D) by a Europa at 3100ft. Blind calls made without success. Standard separation maintained. **EVEKTOR AEROTECHNIK EV97 BOMBARDIER ROTAX** Cruise EGBB (BHX): Birmingham 21/04/2013 201304228 Infringement of the Birmingham CTA (Class D) by an EV97 at 2800ft. Blind transmission made and a/c identified. Standard separation maintained. Pilot error acknowledged. **EVEKTOR AEROTECHNIK EV97 BOMBARDIER ROTAX** EGBP : KEMBLE 02/03/2013 201302178 Unknown Unknown fluid leaking from engine cowling. A/c returned. Emergency services attended. The fluid was reported as being water based and non flammable. Problem resolved and a/c returned to normal operations. **EVEKTOR AEROTECHNIK EV97 BOMBARDIER ROTAX** Taxi to runway EGBP: KEMBLE 05/03/2013 201302303 A/c lined up on runway for take-off when engine stalled. Unable to restart Instructor unable to restart engine after a/c removed from runway assisted by fire service EVEKTOR AEROTECHNIK EV97 **BOMBARDIER ROTAX** 03/05/2013 201304857 En-route Dunsfold Infringement of the LTMA (Class A) and the Gatwick CTA (Class D) by an a/c squawking 7000 indicating 2900ft, 3nm NW of Dunsfold. A/c identified via Mode S as an EV97. Traffic info and avoiding action given. Standard separation maintained. Gatwick departures were stopped. TC gave avoiding action to a departing B737 on a BOG SID **EVEKTOR AEROTECHNIK EV97 BOMBARDIER ROTAX** EGPT (PSL): Perth/Scone Take-off run 20/05/2013 201305756 912 Loss of control during take-off roll caused a/c to depart the runway and travel across the field. During take-off roll, the a/c turned sharp left. Solo student converting to different a/c type (from flex wing to 3 axis) with opposite sense steering. No damage or injuries reported.

EGKA (ESH): Shoreham EXTRA 300 LYCOMING Initial climb 16/02/2013 201302056 540 FAMILY MAYDAY declared on climb out due engine problem. A/c landed safely and taxied back to parking area under own power. FLY BUY ULTRALIGHTS IKARUS BOMBARDIER ROTAX EGHP : Popham 05/05/2013 201305087 Standing: C42 Engine(s) Operating UK Reportable Accident: Passenger vacated a/c and collided with moving propeller. Two POB one minor injuries one no injuries. Subject to AAIB AARF investigation. **FLY BUY ULTRALIGHTS IKARUS BOMBARDIER ROTAX** Emergency Spital Cross 21/04/2013 201304691 C42 912 landing or offrunway landing A/c made forced landing in a field. One POB, no injuries. Reports of damage to fencing on take-off from field. **FLY BUY ULTRALIGHTS IKARUS** BOMBARDIER ROTAX En-route CPT 06/05/2013 201304898 C42 Infringement of the LTMA (Class A) by an Ikarus C42 at 5500ft. No other traffic were affected by this infringement. **FLY BUY ULTRALIGHTS IKARUS BOMBARDIER ROTAX** EGLS : Old sarum 26/05/2013 201306095 Approach C42 UK Reportable Accident: During a crosswind landing the a/c dropped 10ft onto the runway. Two POB no injuries. Subject to AAIB AARF Investigation. LH landing gear damaged. GROB G109 201304910 GROB Thermal lift DTY 06/05/2013 2500 Infringement of the Daventry CTA (Class A) by a G109B at 5200ft. Separation minima was maintained. The pilot stated; 'with minimal experience of a/c in gliding mode he was taking instruction from a more experienced glider pilot on a casual basis. Continual tight turns in strong thermal activity resulted in pilot becoming unaware of position and height.' GROB G115 LYCOMING 29/04/2013 201304928 En-route HON 235 FAMILY Infringement of the Birmingham CTA (Class D) by a G115 at 2000ft. No other traffic were affected by the infringement. GROB G115 LYCOMING 23/04/2013 201305032 Aerobatics EGYD : Cranwell 360 FAMILY

#### RPM decay during display practice.

A progressive level of RPM decay was experienced during the course of the sequence and was unacceptable towards the end of the flight. During the penultimate stall turn, an RPM decay to 1700 was experienced with associated oil pressure drop to 30psi. Tech Log entry made. Engineers report states that following installation of the MT propeller on this a/c type, several confirmed reports of RPM decay have been reported during certain aerobatic manoeuvres especially in vertical or near zero G conditions. The inverted oil system is suspected as being a contributory factor and the manufacturers and maintenance organisations are in consultation. All company owned a/c have been temporarily removed from operation until advice from the OEM has been provided.

	LYCOMING 235 FAMILY	Taxi	EGCB : Manchester/Barton	18/05/2013	201305604
Reporter alleged that the duty	erved to have taxied onto, and su FISO had attempted to call both y had parked on the duty runway	a/c but neither pilots were we	earing headsets. ADM met the two	o pilots as they we	ere walking back from th
GRUMMAN AA5	LYCOMING 320 FAMILY	En-route	EGTE (EXT): Exeter	01/03/2013	201302327
PAN declared due to rough ru	nning engine. A/c returned.				
GRUMMAN AA5	LYCOMING 320 FAMILY	Level off- touchdown	EGTC : Cranfield	01/03/2013	201302703
Runway inspection had been	uch and go's and on both occasi	to a suspected strike but no	orpoised. A/c landed on the third a		
GRUMMAN AA5	LYCOMING 320 FAMILY	Unknown	Luton	12/04/2013	201303847
No other traffic was affected b			g 7000, no Mode C. Separation lo t the plot had had problems with h		
map.					
·	LYCOMING 360 FAMILY	Cruise	EGLL (LHR): London/Heathrow	01/05/2013	201304704
GRUMMAN AA5			London/Heathrow	01/05/2013	201304704
GRUMMAN AA5  Infringement of the London CT  GRUMMAN AA5  Infringement of the LTMA (Cla Blind calls were made without	360 FAMILY  TR (Class A) by a Grumman AA5  LYCOMING 320 FAMILY  ass A) by an a/c, identified via Mo success. Approx 13mins later A/	at 2100ft. Traffic info given.  Climb to cruising level or altitude  de S as an AA5, squawking as was observed in same air.	London/Heathrow  Standard separation maintained.	02/05/2013 Oft. Standard separation of the control	201304719 ration maintained. ting 3000ft. Pilot's repo
GRUMMAN AA5  Infringement of the London CT  GRUMMAN AA5  Infringement of the LTMA (Cla Blind calls were made without Indicates pilot was flying with a	360 FAMILY  TR (Class A) by a Grumman AA5  LYCOMING 320 FAMILY  ass A) by an a/c, identified via Mo success. Approx 13mins later A/	at 2100ft. Traffic info given.  Climb to cruising level or altitude  de S as an AA5, squawking as was observed in same air.	London/Heathrow  Standard separation maintained.  Boreham  7000 with Mode C indicating 3100 space again on Southwest track w	02/05/2013 Oft. Standard separation of the control	201304719 ration maintained. ting 3000ft. Pilot's repo
GRUMMAN AA5  Infringement of the London CT  GRUMMAN AA5  Infringement of the LTMA (Cla Blind calls were made without indicates pilot was flying with a  GRUMMAN AA5  During a crosswind landing the	360 FAMILY  TR (Class A) by a Grumman AA5  LYCOMING 320 FAMILY  ass A) by an a/c, identified via Mo success. Approx 13mins later A/ an instructor on a training check of  LYCOMING 320 FAMILY  e a/c bounced twice and landed h	Climb to cruising level or altitude  de S as an AA5, squawking about the same air exercise and had climbed into	London/Heathrow  Standard separation maintained.  Boreham  7000 with Mode C indicating 3100 space again on Southwest track wo CAS due to believing they were  EGHO: Thruxton	02/05/2013 Oft. Standard sepal vith Mode C indica further East then t	201304719 ration maintained. ting 3000ft. Pilot's reporthey were.
GRUMMAN AA5  Infringement of the London CT  GRUMMAN AA5  Infringement of the LTMA (Cla Blind calls were made without indicates pilot was flying with a  GRUMMAN AA5  During a crosswind landing the Damage found to propeller an	360 FAMILY  TR (Class A) by a Grumman AA5  LYCOMING 320 FAMILY  ass A) by an a/c, identified via Mo success. Approx 13mins later A/ an instructor on a training check of  LYCOMING 320 FAMILY  e a/c bounced twice and landed h	Climb to cruising level or altitude  de S as an AA5, squawking about the same air exercise and had climbed into	London/Heathrow  Standard separation maintained.  Boreham  7000 with Mode C indicating 3100 space again on Southwest track wo CAS due to believing they were  EGHO: Thruxton	02/05/2013 Oft. Standard sepal vith Mode C indica further East then t	201304719 ration maintained. ting 3000ft. Pilot's reporthey were.
GRUMMAN AA5  Infringement of the LTMA (Cla Blind calls were made without indicates pilot was flying with a  GRUMMAN AA5  During a crosswind landing the Damage found to propeller an	360 FAMILY  TR (Class A) by a Grumman AA5  LYCOMING 320 FAMILY  ass A) by an a/c, identified via Mo success. Approx 13mins later A/ an instructor on a training check of  LYCOMING 320 FAMILY  e a/c bounced twice and landed h d engine.  LYCOMING 320 FAMILY	Climb to cruising level or altitude  de S as an AA5, squawking A5 was observed in same air exercise and had climbed into	Boreham  7000 with Mode C indicating 3100 space again on Southwest track wo CAS due to believing they were  EGHO: Thruxton  to strike the ground.	02/05/2013  Oft. Standard separativith Mode C indicate further East then to 01/05/2013	201304719 ration maintained. ting 3000ft. Pilot's report they were. 201305835
GRUMMAN AA5  Infringement of the London CT  GRUMMAN AA5  Infringement of the LTMA (Classified Calls were made without noticates pilot was flying with a GRUMMAN AA5  During a crosswind landing the Damage found to propeller an GRUMMAN AA5	360 FAMILY  TR (Class A) by a Grumman AA5  LYCOMING 320 FAMILY  ass A) by an a/c, identified via Mo success. Approx 13mins later A/ an instructor on a training check of  LYCOMING 320 FAMILY  e a/c bounced twice and landed h d engine.  LYCOMING 320 FAMILY	Climb to cruising level or altitude  de S as an AA5, squawking A5 was observed in same air exercise and had climbed into	Boreham  7000 with Mode C indicating 3100 space again on Southwest track wo CAS due to believing they were  EGHO: Thruxton  to strike the ground.  Cranfield	02/05/2013  Oft. Standard separativith Mode C indicate further East then to 01/05/2013	201304719 ration maintained. ting 3000ft. Pilot's report they were. 201305835

	LYCOMING 320 FAMILY	Unknown	RAF Kenley	28/04/2013	201304717
JK AIRPROX 2013/025 - Military g	lider and a Grumman GA7 at 170	Off at BAE Kanlay			
JABIRU JABIRU	JABIRU 2200	Level off- touchdown	EGNW : Wickenby	02/05/2013	201305562
UK Reportable Accident: Landing g AAIB AARF investigation.	gear bolt snapped on landing and	a/c veered off the runw	vay. Two POB, no injuries. Landir	ng gear and elevato	r damaged. Subject to
JABIRU JABIRU	JABIRU 2200	En-route	EGAA (BFS): Belfast/Aldergrove	16/05/2013	201305529
A Jabiru infringed the Belfast TMA given. Separation minima was mail		l an inbound A319 at 30	000ft to break from finals and rejo	oin for an uneventful	landing. Traffic info
LANCAIR (320)	CONTINENTAL (TELEDYNE) USA 520 FAMILY	Level off- touchdown	EGHS : Henstridge	16/05/2013	201306059
UK Reportable Accident: A/c made investigation.	a heavy landing causing the prop	peller to strike the grou	nd. One POB, no injuries. Damaç	ge to a/c substantial	. Subject to AAIB AARF
LET L410	UNKNOWN	Normal descent	EGNS (IOM): Isle Of Man/Ronaldsway	15/01/2013	201300646
instructed to route to holding faciliti	es with procedural separation est	tablished.			were informed and
instructed to route to holding faciliti ATE switched the PSR back on. Th	es with procedural separation est	tablished.			were informed and 201304818
nstructed to route to holding faciliti ATE switched the PSR back on. The MORANE SAULNIER MS893  Low speed taxi ground collision betaloc commenced taxi when the pilot slow speed until the RH wing contains arrangement in this a/c has been contains and the property of the store of	es with procedural separation est the a/c were vectored for their app LYCOMING 360 FAMILY tween two a/c, one parked. The realised that his application of the toted the LH aileron of the parked at the cause. The brakes we	tablished. roaches. The SSR mor  Taxi to runway  e brakes was having not a/c. The impact has rere not faulty but were b	Old Buckenham Airfield  Deffect, therefore no steering was usulted in cosmetic paint damage eing pressed at the bottom of the	03/05/2013 s available. The a/c to both a/c. Pilot co	201304818  continued forward at onfusion over the pedal
Radar failure. PSR was already u/s instructed to route to holding faciliti ATE switched the PSR back on. The MORANE SAULNIER MS893  Low speed taxi ground collision beta/c commenced taxi when the pilot slow speed until the RH wing conta arrangement in this a/c has been commenced taxingement in the correctly. Bot OTHER (X air)	es with procedural separation est the a/c were vectored for their app LYCOMING 360 FAMILY tween two a/c, one parked. The realised that his application of the toted the LH aileron of the parked at the cause. The brakes we	tablished. roaches. The SSR mor  Taxi to runway  e brakes was having not a/c. The impact has rere not faulty but were b	Old Buckenham Airfield  Deffect, therefore no steering was usulted in cosmetic paint damage eing pressed at the bottom of the	03/05/2013 s available. The a/c to both a/c. Pilot co	201304818  continued forward at infusion over the pedal
instructed to route to holding faciliti ATE switched the PSR back on. Th MORANE SAULNIER MS893  Low speed taxi ground collision bet A/c commenced taxi when the pilot slow speed until the RH wing conta arrangement in this a/c has been c would have operated correctly. Bot	es with procedural separation estate a/c were vectored for their app  LYCOMING 360 FAMILY  tween two a/c, one parked. realised that his application of the toted the LH aileron of the parked ited as the cause. The brakes we ha/c to be inspected by licensed  BOMBARDIER ROTAX  d by an unknown station on permatereral times but could not hear AT	tablished. roaches. The SSR more  Taxi to runway  e brakes was having not a/c. The impact has refer not faulty but were bengineers before furthed.  Unknown  anent transmit for exter CC response. A/c's transmit for exter contents and the second sec	Old Buckenham Airfield  Old Buckenham Airfield  o effect, therefore no steering wasulted in cosmetic paint damage eing pressed at the bottom of the er flight.  EGDG (NQY): St. Mawgan  asive periods. smissions and DF trace correspo	n shortly after.  03/05/2013  s available. The a/c to both a/c. Pilot co pedal rather than a 02/03/2013	201304818  continued forward at infusion over the pedal at the top, whereby they  201302162
instructed to route to holding faciliti ATE switched the PSR back on. The MORANE SAULNIER MS893  Low speed taxi ground collision beto A/c commenced taxi when the pilot slow speed until the RH wing contains arrangement in this a/c has been convolud have operated correctly. Bot OTHER (X air)  Approach/Radar frequency blocked X'Air microlight attempted to call see	es with procedural separation estate a/c were vectored for their app  LYCOMING 360 FAMILY  tween two a/c, one parked. realised that his application of the toted the LH aileron of the parked ited as the cause. The brakes we ha/c to be inspected by licensed  BOMBARDIER ROTAX  d by an unknown station on permatereral times but could not hear AT	tablished. roaches. The SSR more  Taxi to runway  e brakes was having not a/c. The impact has refer not faulty but were bengineers before furthed.  Unknown  anent transmit for exter CC response. A/c's transmit for exter contents and the second sec	Old Buckenham Airfield  Old Buckenham Airfield  o effect, therefore no steering wasulted in cosmetic paint damage eing pressed at the bottom of the er flight.  EGDG (NQY): St. Mawgan  asive periods. smissions and DF trace correspo	n shortly after.  03/05/2013  s available. The a/c to both a/c. Pilot co pedal rather than a 02/03/2013	201304818  continued forward at infusion over the pedal at the top, whereby they  201302162
Instructed to route to holding facilitic ATE switched the PSR back on. The MORANE SAULNIER MS893  Low speed taxi ground collision beto A/c commenced taxi when the pilot slow speed until the RH wing contains arrangement in this a/c has been consuld have operated correctly. Bot OTHER (X air)  Approach/Radar frequency blocked X'Air microlight attempted to call septimary radar returns were observed OTHER (MCR01)	LYCOMING 360 FAMILY  tween two a/c, one parked. realised that his application of the parked as the cause. The brakes we ha/c to be inspected by licensed  BOMBARDIER ROTAX  d by an unknown station on permaneral times but could not hear All and in the vicinity of Truro airfield. N	tablished. roaches. The SSR more  Taxi to runway  e brakes was having not a/c. The impact has refere not faulty but were bengineers before furthed.  Unknown  anent transmit for exter CC response. A/c's transon to other a/c on frequence.	Old Buckenham Airfield  o effect, therefore no steering was usulted in cosmetic paint damage eing pressed at the bottom of the er flight.  EGDG (NQY): St. Mawgan  assive periods.  smissions and DF trace corresponds.  smissions and DF trace corresponds.	n shortly after.  03/05/2013  s available. The a/c to both a/c. Pilot co a pedal rather than a 02/03/2013  onded with the perm	201304818  continued forward at infusion over the pedal at the top, whereby they  201302162  anent transmit station and
instructed to route to holding faciliti ATE switched the PSR back on. The MORANE SAULNIER MS893  Low speed taxi ground collision beto the commenced taxi when the pilot slow speed until the RH wing contains arrangement in this a/c has been contained to the commenced taxi. When the pilot slow speed until the RH wing contains arrangement in this a/c has been contained to contain the contained to t	LYCOMING 360 FAMILY  tween two a/c, one parked. realised that his application of the parked as the cause. The brakes we ha/c to be inspected by licensed  BOMBARDIER ROTAX  d by an unknown station on permaneral times but could not hear All and in the vicinity of Truro airfield. N	tablished. roaches. The SSR more  Taxi to runway  e brakes was having not a/c. The impact has refere not faulty but were bengineers before furthed.  Unknown  anent transmit for exter CC response. A/c's transon to other a/c on frequence.	Old Buckenham Airfield  o effect, therefore no steering was usulted in cosmetic paint damage eing pressed at the bottom of the er flight.  EGDG (NQY): St. Mawgan  assive periods.  smissions and DF trace corresponds.  smissions and DF trace corresponds.	o3/05/2013  s available. The a/c to both a/c. Pilot co pedal rather than a 02/03/2013  onded with the perm	201304818  continued forward at infusion over the pedal at the top, whereby they  201302162  anent transmit station and

	LYCOMING 360 FAMILY	En-route	Ercal Heath	03/05/2013	201304855
/c declared MAYDAY just outside Sha &D reported that the pilot had contact	_			Shawbury.	
OTHER (MICROLIGHT)	BOMBARDIER ROTAX 912	En-route	Hunsdon	05/05/2013	201304882
ofringement of the Stansted TMZ 2 (C witched on.	lass G) by a Skyranger trackir	ng Southbound. No oth	er a/c affected. It seems that the	pilot believed that h	nis transponder was
THER (MICROLIGHT)	BOMBARDIER ROTAX	Landing roll - on runway	EGHP : Popham	05/05/2013	201305577
K Reportable Accident. Runway excu	ursion on landing roll, collision	with ground object. Tw	o POB no injuries. Subject to A/	AIB AARF investigat	ion.
THER (MICROLIGHT)	BOMBARDIER ROTAX	Landing roll - on runway	Berkshire	03/05/2013	201305684
IK Reportable Accident: Nosewheel a	nd right wheel collapsed on la  BOMBARDIER ROTAX 912	nding. Two POB, no inj	uries. A/c damaged. Subject to Sandford St Martin	AAIB AARF investig	pation. 201305774
	912				
	engine problems after take-off	and made a forced lan	ding in a field. Two POB, no inju	uries. A/c substantial	lly damaged. Subject to
AAIB AARF investigation.	engine problems after take-off  BOMBARDIER ROTAX 912	and made a forced lan	ding in a field. Two POB, no inju	18/05/2013	lly damaged. Subject to
AAIB AARF investigation.  DTHER (Skyranger Swift 912S)	BOMBARDIER ROTAX 912	Cruise			
OTHER (Skyranger Swift 912S)  Infringement of the Maastricht TMA (Cl	BOMBARDIER ROTAX 912	Cruise			
OTHER (Skyranger Swift 912S)  Infringement of the Maastricht TMA (Clarent Control of the Maastri	BOMBARDIER ROTAX 912 lass D) by a Skyranger 912S a  JABIRU 2200 actice display. Damage to pro	Cruise at 2000ft.  Low flying	Maastricht	18/05/2013	201306048
JK Reportable Accident: A/c suffered of AAIB AARF investigation.  DTHER (Skyranger Swift 912S)  Infringement of the Maastricht TMA (Clarent Control of the Maastricht TMA (Cla	BOMBARDIER ROTAX 912 lass D) by a Skyranger 912S a  JABIRU 2200 actice display. Damage to pro	Cruise at 2000ft.  Low flying	Maastricht	18/05/2013	201306048

PERCIVAL P10VEGA GULL DE HAVILLAND Take-off EGKB (BQH): Biggin hill 12/05/2013 201305238 Serious Incident: A/c lost tail wheel on departure from runway. Full emergency landing was performed with no further incident. One POB, no injuries. Subject to AAIB AARF investigation PIEL CP301 CONTINENTAL EGBB (BHX): Birmingham 19/04/2013 201304173 En-route (TELEDYNE) USA 200 FAMILY Infringement of the Birmingham CTA1 (Class D) by a Piel CP301 at 2200ft. A/c identified and clearance given to continue transit not above 2500ft. No traffic affected. Standard separation maintained. PIPER PA18 CONTINENTAL Initial climb EGTB: Wycombe Air 18/05/2013 201306058 (TELEDYNE) USA Park/Booker Other UK Reportable Accident: A/c suffered engine failure after take-off and landed in a field. One POB, no injuries. A/c substantially damaged. Subject to AAIB AARF investigation. PIPER PA22 LYCOMING Landing roll - on EGTR : Elstree 25/05/2013 201305944 320 FAMILY runway UK Reportable Accident: Brakes failed on landing and a/c left the runway, travelled across grass and through a fence coming to rest nose down in a ditch. Three POB, no injuries. A/c damage TBC. Subject to AAIB AARF investigation. **PIPER PA23** EGNS (IOM): Isle Of 18/05/2013 201305652 LYCOMING Taxi to runway 540 FAMILY Man/Ronaldswav Runway incursion. PA27 instructed to Hold D1 for R/W26 was observed to cross D1 and enter R/W26 glidepath critical area. PA27 was informed they had crossed D1 and was instructed to taxi back to D1. ATC commented there was an on-going issue of pilots crossing D1 despite extra runway guard lights being placed at this position, and suggested that extra signage maybe required. ATS management noted that suggestions for additional signage would help alleviate the risk and stated that the Airport authorities had also taken note of the risk. LYCOMING EGBP : KEMBLE 03/03/2013 PIPER PA28 Taxi 201302325 320 FAMILY Tie-down still attached to port wing during taxi. A/c observed by ATC to have a tie-down attached. A/c informed immediately but pilot had also realised and was in the process of shutting down the engine. PIPER PA28 LYCOMING 21/03/2013 201302982 Unknown EGBO: WOLVERHAMPTON 320 FAMILY Fuel filler cap found on runway. A/c elected to continue with cap missing. 01/04/2013 201303334 PIPER PA28 LYCOMING Cruise En route 360 FAMILY Loss of communications due to temporary radio failure. Controller passed details to D&D and coordinated action with FIR controller. Pilot then called up on hand held radio and confirmed that he was continuing to destination. Shortly afterwards the a/c radio recovered and was able to transmit. PIPER PA28 LYCOMING En-route EGBB (BHX): Birmingham 19/04/2013 201304174 320 FAMILY Infringement of the Birmingham CTA 4 (Class D) by a PA28 at 3800ft. Standard separation maintained. No traffic affected.

PIPER PA28 LYCOMING Climb to cruising WOD 20/04/2013 201304187 360 FAMILY level or altitude Infringement of the London TMA (Class A) by a PA28 squawking 0452 at 2700ft. CAIT activated. Traffic info given. A/c identity confirmed with Mode S. Heathrow INT director telephoned Farnborough who advised it was under control and the contact promptly descended below CAS. PIPER PA28 LYCOMING En-route SAM 23/04/2013 201304310 320 FAMILY Infringement of the Southampton CTA (Class D) by an unknown a/c squawking 7000 resulting in loss of separation with a DA40. Bournemouth ATC identified a/c via Mode S as a PA28. Traffic info given. Bandboxed Solent Radar ATCO operating SSR only, due to unscheduled maintenance work on Southampton radar, observed a 7000 squawk outside CAS but getting close to CTA. ATCO made a blind call which went unanswered. ATCO then instructed an IFR transit DA40 to make a turn away from the infringer, however separation was lost when infringer entered CAS behind the DA40. Infringement submission report revealed the pilot regretted the incursion and that although the area was well known to them, in future flights the pilot would contact ATC when flying within 10nm of the area/zone. PIPER PA28 LYCOMING En-route Haverhill 25/04/2013 201304487 320 FAMILY Infringement of the Stansted CTA (Class D) by a PA28. Inbound a/c delayed. Traffic info given. Standard separation maintained. PIPER PA28 LYCOMING Climb to cruising EGTR : Elstree 28/04/2013 201304501 320 FAMILY level or altitude Infringement of the London TMA (Class A) by a PA28 squawking 7000 with Mode C indicating 2800ft. Separation lost with an HS125 inbound Northolt that was vectored away and delayed. Traffic info and avoiding action given. Infringer identified by Farnborough North via a call from Northolt. Operator fully alerted. PIPER PA28 LYCOMING Cruise D128 and D125 30/04/2013 201304685 320 FAMILY Infringement of active Danger Areas D128 and D125 by a PA28 student pilot with instructor at 2700ft on VFR NAVEX. Live firing suspended. ATC contacted various ATC units, none of whom appeared to be working the PA28. D&D contacted to track the PA28 on VHF guard frequency. At this point the PA28 squawk changed from 2065 to 2650. PA28 had allegedly selected the wrong squawk. PIPER PA28 LYCOMING Cruise EGLC (LCY): London city 01/05/2013 201304702 320 FAMILY Infringement of the London City CTA (Class D) by a student pilot flying a PA28 at 1900ft. Standard separation maintained. Traffic info given. Thames controller vectored an inbound London City a/c to ensure required spacing. PA28 student pilot was in contact with Farnborough LARS who stated they had instructed PA28 not to be above 1400ft and/or to turn Southbound immediately, but the turn had not been made and despite repeated instructions and the descent not made until 1.5nm inside CAS. Farnborough LARS then issued instructions to vector the PA28 out of CAS. CFI has been contacted and the pilot is to undertake extra navigational exercises. PIPER PA28 LYCOMING En-route Warrington 02/05/2013 201304763 320 FAMILY Infringement of the Manchester CTR (Class D) by a PA28 at 1800ft squawking 7000. Traffic info given. Standard separation maintained. Pilot apologised for his error. PIPER PA28 LYCOMING Cruise EGKK (LGW): 05/05/2013 201304872 360 FAMILY London/Gatwick Infringement of the Gatwick CTR (Class D) by a PA28 at 2000ft. Standard separation maintained. PIPER PA28 LYCOMING D702 04/05/2013 201304873 Approach

Infringement of active Danger Area D702 by a PA28 at 1000ft.

320 FAMILY

Controller observed the a/c heading towards the Danger Area and alerted the pilot, however, the a/c continued ahead into the area. Controller advised a/c to vacate the area immediately.

LYCOMING 360 FAMILY	Taxi to runway	EGJB (GCI): Guernsey, Channel Is.	06/05/2013	201304990
issued and pilot was immediate	ly instructed to vacate the ru			
LYCOMING 320 FAMILY	Take-off: Other (Touch and Go)	EGKH : Lashenden/Headcorn	07/05/2013	201305028
go and subsequently flew into clo	se proximity with a parachuti	st.		
LYCOMING 360 FAMILY	En-route	En-route	16/04/2013	201305443
call to Denham airfield, whose A	TZ the PA28 had subsequer	ntly entered, to instruct the PA28		
LYCOMING 320 FAMILY	Cruise	Goodwood	16/05/2013	201305516
Class A) by a PA28 at FL081. Sta	andard separation maintaine	d.		
LYCOMING 360 FAMILY	Change of cruise level	EGLC (LCY): London city	18/05/2013	201305618
tion maintained.			D) with Mode C ind	icating 1900ft overhead
LYCOMING 360 FAMILY	Cruise	EGLC (LCY): London city	22/05/2013	201305776
			_	
LYCOMING 320 FAMILY	Unknown	EGBP : KEMBLE	16/05/2013	201306019
8 and a PA18 at 1000ft, downwir	nd for R/W26 at Kemble.			
	Taxi from runway	EGNH (BLK): Blackpool	16/05/2013	201305526
LYCOMING 320 FAMILY	, a.u o a a,			
	taxiway light which subseque		eing closed until FO	D was removed.
320 FAMILY tate they had hit and smashed a	taxiway light which subseque		eing closed until FO	D was removed. 201305655
	C behind a red stop-bar annound issued and pilot was immediate a subsequently re-cleared to land LYCOMING 320 FAMILY  To and subsequently flew into close and subsequently.  To Class A) and Northolt RMA be a call to Denham airfield, whose A failed to comply with the instruction.  LYCOMING 320 FAMILY  MA (Class A) by a PA28 at FL081. State and subsequently flew into maintained.  River Thames as it passed a pole and subsequently set a QNH of 1008mb and subs	C behind a red stop-bar announced he was lining up at the sate issued and pilot was immediately instructed to vacate the runs subsequently re-cleared to land.  LYCOMING 320 FAMILY Take-off: Other (Touch and Go)  go and subsequently flew into close proximity with a parachuti  LYCOMING 360 FAMILY  TR (Class A) and Northolt RMA by an a/c, later identified as a call to Denham airfield, whose ATZ the PA28 had subsequer failed to comply with the instruction and separation may have  LYCOMING 320 FAMILY  Class A) by a PA28 at FL081. Standard separation maintained.  LYCOMING 360 FAMILY  Class A) by a PA28 squawking 7000 at 2600ft. A/c also entition maintained.  River Thames as it passed a police helicopter working 125.62  LYCOMING 360 FAMILY  SS A) by a PA28 at 2700ft resulting in a loss of separation againteently set a QNH of 1008mb on departure instead of a contraction.	C behind a red stop-bar announced he was lining up at the same time as taxing across the st i issued and pilot was immediately instructed to vacate the runway and a landing clearance for subsequently re-cleared to land.  LYCOMING 320 FAMILY Touch and Go)  LYCOMING 320 FAMILY Touch and Go)  LYCOMING 360 FAMILY TR (Class A) and Northolt RMA by an a/c, later identified as a PA28, at 1300ft. Separation may call to Denham airfield, whose ATZ the PA28 had subsequently entered, to instruct the PA28 lated to comply with the instruction and separation may have been lost as a result.  LYCOMING 320 FAMILY  Class A) by a PA28 at FL081. Standard separation maintained.  LYCOMING 320 FAMILY  Class A) by a PA28 squawking 7000 at 2600ft. A/c also entered the Stansted CTA (Class tition maintained.  River Thames as it passed a police helicopter working 125.625.  LYCOMING 360 FAMILY  Cruise EGLC (LCY): London city and parameters are some content of the stansted CTA (Class tition maintained.  River Thames as it passed a police helicopter working 125.625.  LYCOMING 360 FAMILY  Cruise EGLC (LCY): London city and parameters are some content of the Stansted CTA (Class tition maintained).  LYCOMING 360 FAMILY  EGLC (LCY): London city and parameters are some content of the Stansted CTA (Class tition maintained).  LYCOMING 360 FAMILY  EGLC (LCY): London city and parameters are some content of the Stansted CTA (Class tition maintained).  LYCOMING 360 FAMILY  EGLC (LCY): London city and parameters are some content of the Stansted CTA (Class tition maintained).	C behind a red stop-bar announced he was lining up at the same time as taxing across the stopbar. Traffic into go issued and pilot was immediately instructed to vacate the runway and a landing clearance for DHC8 was cancel is subsequently re-cleared to land.  LYCOMING 320 FAMILY Take-off: Other EGKH: 320 FAMILY Touch and Go) Lashenden/Headcorn  Take-off: Other EGKH: 320 FAMILY Take-off: Other Standard Separation maintained. Take-off: Other EGKH: 320 FAMILY Take-off: Other EGKH: 320 FAMILY Take-off: Other Standard Standard Separation maintained. Take-off: Other EGKH: 320 FAMILY Take-off: Other Standard Standa

PIPER PA28	LYCOMING 320 FAMILY	En-route	EGPE (INV): Inverness	28/03/2013	201303293
PAN declared due to magneto	problem at 1500ft. A/c landed with t	fire services in attendance	<b>3.</b>		
PIPER PA28	LYCOMING 320 FAMILY	Standing : Engine(s) Not Operating	EGFF (CWL): Cardiff	31/03/2013	201303315
	rom a previous flight, was parked under. Er. Emergency services attended the	•	•		
PIPER PA28	LYCOMING 360 FAMILY	Landing roll - on runway	EGSH (NWI): Norwich	07/05/2013	201305151
Vc swerved on landing and sl	ewed off the LH side of the runway.	One POB with no injuries	and no damage caused to the a	a/c.	
PIPER PA28	THIELERT Centurion 1.7 (TAE 125)	Non-scheduled maintenance	EGBO: WOLVERHAMPTON	27/05/2013	201305978
• '	found to be loose. main wheel following a tyre change op spar screws and three of the lowe	r spar bolts to be loose. T	he fourth lower bolt had sheared	d off and was seen t	o be heavily rusted.
	gests fretting damage to the spar cap he operator.	os and elongation of the b	oit noies. Cracks were visible or	Title upper leg casir	ig. Reporter is not the a
naintainer and has informed t		ss and elongation of the b	EGPN (DND): Dundee (Riverside Park)	28/03/2013	201303262
PIPER PA28 PAN declared and a/c returned	LYCOMING 360 FAMILY  d due to an unidentified door probler	Initial climb	EGPN (DND): Dundee		
PIPER PA28 PAN declared and a/c returned and a/c returned and a/c landed safely with emerger	LYCOMING 360 FAMILY  d due to an unidentified door probler	Initial climb	EGPN (DND): Dundee		
PIPER PA28 PAN declared and a/c returned to landed safely with emerge PIPER PA28 PA28 departed R/W23 without the controller's response was to large returned to safely with emerge PIPER PA28	LYCOMING 360 FAMILY  d due to an unidentified door probler ncy services in attendance.  LYCOMING	Initial climb  n.  Take-off run  id not hear the departure ere affected. s the pilot had a long trans	EGPN (DND): Dundee (Riverside Park)  EGNV (MME): TEESSIDE  request and only heard a direction of the content of	28/03/2013  14/04/2013  on of turn out questing winds and possib	201303262  201303887 ion. The pilot assumed
PIPER PA28  PAN declared and a/c returned to landed safely with emerger  PIPER PA28  PA28 departed R/W23 without the controller's response was larger to safe controller elected not to safe controller elected not to safe controller.	LYCOMING 360 FAMILY  d due to an unidentified door probler ncy services in attendance.  LYCOMING 360 FAMILY  t take-off clearance. The controller d take-off clearance. No other traffic way anything to the pilot at the time as	Initial climb  n.  Take-off run  id not hear the departure ere affected. s the pilot had a long trans	EGPN (DND): Dundee (Riverside Park)  EGNV (MME): TEESSIDE  request and only heard a direction of the content of	28/03/2013  14/04/2013  on of turn out questing winds and possib	201303262  201303887  ion. The pilot assumed
PIPER PA28  PAN declared and a/c returned to a controller service and a	LYCOMING 360 FAMILY  d due to an unidentified door probler ncy services in attendance.  LYCOMING 360 FAMILY  t take-off clearance. The controller d take-off clearance. No other traffic way anything to the pilot at the time as oilot's mind. The controller notified W  CONTINENTAL (TELEDYNE) USA 360 FAMILY	Initial climb  Take-off run  id not hear the departure ere affected. Is the pilot had a long trans sycombe ATC to let the pilot had a long trans sycombe area. Damage to nosewhole area. Damage to nosewhole	EGPN (DND): Dundee (Riverside Park)  EGNV (MME): TEESSIDE  request and only heard a direction of the control of	28/03/2013  14/04/2013  on of turn out questing winds and possiblaised.  25/05/2013	201303262  201303887  ion. The pilot assumed ally arriving in the dark an 201305939
PIPER PA28  PAN declared and a/c returned to land a	LYCOMING 360 FAMILY  d due to an unidentified door probler ncy services in attendance.  LYCOMING 360 FAMILY  t take-off clearance. The controller d take-off clearance. No other traffic way anything to the pilot at the time as oilot's mind. The controller notified W  CONTINENTAL (TELEDYNE) USA 360 FAMILY  ormal landing. then veered to the right onto grass a	Initial climb  Take-off run  id not hear the departure ere affected. Is the pilot had a long trans sycombe ATC to let the pilot had a long trans sycombe area. Damage to nosewhole area. Damage to nosewhole	EGPN (DND): Dundee (Riverside Park)  EGNV (MME): TEESSIDE  request and only heard a direction of the control of	28/03/2013  14/04/2013  on of turn out questing winds and possiblaised.  25/05/2013	201303262  201303887  ion. The pilot assumed ally arriving in the dark an 201305939
PIPER PA28  PAN declared and a/c returned to land a safely with emerger lan	LYCOMING 360 FAMILY  d due to an unidentified door probler ncy services in attendance.  LYCOMING 360 FAMILY  t take-off clearance. The controller d take-off clearance. No other traffic way anything to the pilot at the time as silot's mind. The controller notified W  CONTINENTAL (TELEDYNE) USA 360 FAMILY  ormal landing. then veered to the right onto grass and destination without having repairs of LYCOMING	Initial climb  Take-off run  id not hear the departure ere affected. Is the pilot had a long transfycombe ATC to let the pilot had a long transfycombe ATC to let on runway  Landing roll - on runway  area. Damage to nosewhadone. Destination airfield a	EGPN (DND): Dundee (Riverside Park)  EGNV (MME): TEESSIDE  request and only heard a directive sit to Wycombe Air Park, in strong to know that a report would be recorded to the company of	28/03/2013  14/04/2013  on of turn out questing winds and possiblaised.  25/05/2013  ck ground. After spefects.	201303262  201303887  ion. The pilot assumed ally arriving in the dark an 201305939  aking with engineer, pilot
PIPER PA28  PAN declared and a/c returned to a common and the piper pa28  PA28 departed R/W23 without the controller's response was a controller elected not to said not want it playing on the payor paper pa28  PIPER PA28  Runway excursion following now a common and	LYCOMING 360 FAMILY  d due to an unidentified door probler ncy services in attendance.  LYCOMING 360 FAMILY  t take-off clearance. The controller d take-off clearance. No other traffic way anything to the pilot at the time as silot's mind. The controller notified W  CONTINENTAL (TELEDYNE) USA 360 FAMILY  ormal landing. then veered to the right onto grass and destination without having repairs of LYCOMING 360 FAMILY	Initial climb  Take-off run  id not hear the departure ere affected. Is the pilot had a long transfycombe ATC to let the pilot had a long transfycombe ATC to let on runway  Landing roll - on runway  area. Damage to nosewhadone. Destination airfield a	EGPN (DND): Dundee (Riverside Park)  EGNV (MME): TEESSIDE  request and only heard a directive sit to Wycombe Air Park, in strong to know that a report would be recorded to the company of	28/03/2013  14/04/2013  on of turn out questing winds and possiblaised.  25/05/2013  ck ground. After spefects.	201303262  201303887  ion. The pilot assumed ally arriving in the dark an 201305939  aking with engineer, pilot

PIPER PA31 LYCOMING Landing roll - off EGBK (ORM): 08/05/2013 201305306 540 FAMILY runway Northampton/Sywell Runway overrun. Pilot perceived that brakes were not working as expected. Investigation found nothing unusual, however the brakes were back-bled as a precaution and subsequent brake performance check was satisfactory. It is thought possible that the pilot did not brake properly, he may not have applied full pressure to the correct part of the brake pedals or, he may have braked late. The pilot was adamant that he braked hard and fully but the a/c did not slow down. The company's safety sub-committee have taken appropriate action. PIPER PA31 LYCOMING En-route EGMD (LYX): Lydd 08/05/2013 201305417 540 FAMILY LH MLG unsafe gear indication. Several flypast inspections carried out which confirmed gear down. A/c landed safely. Local standby called. PIPER PA31 LYCOMING 18/05/2013 201305606 Initial climb LFAT (LTQ): Le Touquet 540 FAMILY Paris-Plage PAN declared and a/c returned due to rough running engine. Flaps failed to extend on approach. After retracting undercarriage, pilot saw the LH engine vibrating and although indications were normal elected to declare PAN and return. Flap selection failed after three attempts and a/c made a flapless landing. **PIPER PA31** EGAA (BFS): UNKNOWN Approach : Other 24/05/2013 201305926 Belfast/Aldergrove Local standby initiated due to reported undercarriage problem. Pilot reported only two green lights illuminated and that the LH main landing gear was indicating in the retracted position. A flypast inspection was carried out. The pilot reported that he now had three green lights and with visual confirmation from the ATCO on duty that all three wheels were deployed, the decision was made to position downwind for approach. The a/c landed safely with emergency services in attendance. **PIPER PA32** 28/04/2013 201305252 LYCOMING En-route 540 FAMILY Charleroi/Brissels South Infringement of CAS (Class C) 10nm Northeast of Charleroi, Brussels, by a PA32 at 4000ft. Traffic info and avoiding action given. ATC instructed a descending B737 to left turn 70deg to ensure separation from PA32. PIPER PA32R LYCOMING Landing roll - on EGSX : North Weald 16/05/2013 201306037 540 FAMILY runwav UK Reportable Accident: Following an in flight return landing gear collapsed on landing. Two POB no injuries. Subject to AAIB AARF Investigation. PIPER PA32R UNKNOWN Taxiing: Other EGTC : Cranfield 03/04/2013 201303514 Taxiway incursion by a PA32. The a/c had taxied without clearance from ATC and pulled out in front of a PA38 that was taxiing to its parking bay. **PIPER PA34** UNKNOWN Climb to cruising EGTK (OXF): 15/02/2013 201301620 level or altitude Oxford/Kidlington VFR PA34 was observed to have climbed through 2000ft, contrary to the LOA resulting in ATC stopping an IFR PA34's descent, on the NDB 19 approach, at 3500ft. VFR PA34 reached a maximum level of 2500ft. Traffic info and avoiding action given. LOA with the operator states, VFR departures will not climb above 2000ft within 5nm of Oxford airport unless approved otherwise. PIPER PA34 UNKNOWN En-route BRI 04/03/2013 201302256 Callsign confusion between fltnums 26 and 66, same operator.

PIPER PA34 LYCOMING En-route **Brentford** 06/05/2013 201304895 360 FAMILY Loss of separation between a PA34 operating SVFR inside the London CTR (Class A) and a Heathrow inbound airliner. Traffic info given. PIPER PA38 LYCOMING EGGP (LPL): Liverpool 25/04/2013 201304429 Approach 235 FAMILY UK AIRPROX 2013/022 - A319 during initial climb at 850ft and a PA38, 1nm West of threshold R/W09. A319 IMC at the time received TCAS TA. Traffic info given. PIPER PA42 PRATT & WHITNEY Landing roll - off EGEO (OBN): OBAN 18/04/2013 201304086 (CANADA) runwav PT-6 FAMILY Burst tyre on landing caused a/c to veer off runway and breaking a runway edge light. On touchdown over braking led to a LH main tyre burst. Directional control was established and a/c brought safely to a stop. Fire services attended. A/c taxied to a parking area and passengers safely disembarked. **PIPER PA44** LYCOMING Normal descent EGBE (CVT): Coventry 22/01/2013 201300551 360 FAMILY Alleged inaccurate TAF for Coventry. Prior to departure, PA44 checked the Wx and TAF. The TAF issued at 1100hrs had forecast, at worst, 7k visibility and BKN at 600ft. The weather report on ATIS prior to PA44 's approach at 1146hrs was 1200m and BKN at 100ft. After landing PA44 checked ATIS again, the 1150hrs Wx was 600m and BKN 100ft. EGKA (ESH): Shoreham PIPER PA44 LYCOMING Final approach 02/03/2013 201302316 360 FAMILY Landing gear panel not indicating three green lights. Flypast inspection carried out and tower confirmed gear down. Full emergency initiated. After holding, the problem had been rectified so the full emergency was downgraded. A/c landed safely. **RAYTHEON 390** UNKNOWN Take-off EGLF (FAB): Farnborough 201305345 civil Raytheon 390 instructed to line up and wait R/W24 was observed getting airborne. Cleared for take-off instruction was never issued. Traffic info given. Crew had made the mistake of setting thrust and initiating the take-off roll. P1 comments that he was concerned that with the combination of the FO's initial doubt about take-off clearance and unusual re-clearance during the take-off roll. On speaking with ATC crew were informed that radar control were concerned that they had not given a release to Tower. This was during a period of high coordinated workload and the Tower controller was unsure, if a take-off clearance had been given. After listening to the tapes it was confirmed that no take-off clearance had given. A climb into CAS was subsequently coordinated with LTCC. **RAYTHEON 390** UNKNOWN Cruise Mayfield 20/05/2013 201305693 Loss of separation between an A320 and a Raytheon 390 due to Raytheon 390 tracking West of their cleared route. Raytheon 390 received TCAS TA. Avoiding action given. **ROCKWELL 112** LYCOMING Take-off run Top Farm 17/02/2013 201302193 360 FAMILY Propeller strike. On take-off on soft ground, a/c accelerated and throttle then retarded. A/c veered to the left and the engine stopped causing the propeller to strike the ground at slow speed. Damage to engine and propeller. SHORT SC7 GARRET AIRESEARCH 03/05/2013 201305012 Landing roll - off Weston-on-the-Green **TPE 331 FAMILY** runway UK Reportable Accident: Nose wheel collapsed on landing. Four POB, no injuries. A/c came to a halt within 100m slightly off to the right of the runway. Subject to AAIB AARF investigation.

SOCATA TB10 LYCOMING En-route Solent CTA 30/04/2013 201304642 360 FAMILY Infringement of the Solent CTA (Class D) by a Socata TB10 at 3700ft squawking 7000. Blind calls made without success. Standard separation maintained. No traffic affected. During thermal activity the pilot failed to reduce engine power early enough **SOCATA TB20** LYCOMING En-route EGSS (STN): 03/05/2013 201304859 540 FAMILY London/Stansted Infringement of the Stansted TMZ (Class G) by a TB20 squawking 7000 at 1700ft. The a/c initially talking to Andrewsfield, then transferred to LTCC. The infringement caused a delay to an inbound B737. SOCATA TB20 LYCOMING Maastricht 12/05/2013 201306005 Unknown 540 FAMILY Infringement of the Maastricht CTR (Class C) and the TMA by a TB20 at 4000ft. STEARMAN PT13 CONTINENTAL EGBJ (GLO): 13/05/2013 201305274 En-route (TELEDYNE) USA Gloucestershire 670 FAMILY MAYDAY declared and forced landing made approx 8nm NNE of the airfield. Controller received the MAYDAY call and despatched a fire vehicle and a departing a/c towards the area. The a/c was located and reported safe. Civil emergency services were directed to the scene. TECNAM (P2006T) BOMBARDIER ROTAX Normal descent EGBE (CVT): Coventry 20/03/2013 201303544 PAN declared due to smoke in the cockpit. A/c was given immediate landing clearance and landed safely with emergency services in attendance. VANS RV4 LYCOMING Cruise EGSS (STN): 03/05/2013 201304858 320 FAMILY London/Stansted Vans RV4 transponder indicated the a/c was at 2800ft instead of actual 1100ft resulting in TC believing Vans RV4 had infringed LTMA (Class A). Traffic info and TC gave avoiding action to a Stansted inbound A320, a Stansted inbound B737 was also delayed. **VANS RV6** LYCOMING EGMC (SEN): Southend 01/05/2013 201304703 En-route 320 FAMILY UK AIRPROX 2013/029- A319 and a Vans RV6, 8nm Southwest of Southend. Traffic info and avoiding action given. VANS RV7 **UNKNOWN** (Superior EGHE (ISC): Scilly Isles/St. 03/05/2013 201304862 Taxi from runway XP-IO-360-B1A2) Mary's A/c made RH turn to vacate runway. Struck and damaged runway light. No significant damage to a/c. VANS RV9 LYCOMING 25/05/2013 201305930 Cruise EGHI (SOU): Southampton 320 FAMILY Infringement of Airway Q41 (Class A) by a Vans RV9 at 4000ft resulting in a loss of separation against a Southampton outbound Trislander. Traffic info and avoiding action given.

YAKOVLEV YAK52	IVCHENKO	Cruise	EGMC (SEN): Southend	23/04/2013	201304309	
	Other					

Infringement of the LTMA (Class A) by a Yak 52 at 5000ft. Inbound a/c delayed. Standard separation maintained.

A/c part of a formation training flight with two other a/c in formation. It is believed that the a/c may have been operating with a faulty transponder. The other possibility is that the altimeter lags due to the type of manoeuvres conducted in a high energy a/c. Both possibilities to be investigated by the operator.

# OCCURRENCE LISTING Aircraft Below 5700kg OCCURRENCES RECORDED BETWEEN 01 May 2013 and 31May 2013

#### ROTARY WING AIRCRAFT

**AEROSPATIALE AS350** TURBOMECA, Cruise En route 18/03/2013 201302926 **FRANCE** ARRIEL Inadvertent raising of collective lever, causing transient over torque. Pilot's watch strap got caught on the scroll switch on the lower left side of the collective lever AEROSPATIALE AS350 TURBOMECA, EGNS (IOM): Isle Of 19/05/2013 201305653 Unknown **FRANCE** Man/Ronaldswav ARRIEL Infringement of the Isle of Man CTR (Class D) by a AS350 squawking 4552. On establishing contact with ATC pilot allegedly made inappropriate comments and did not seem to understand the importance of obtaining a clearance before entering CAS. **AEROSPATIALE AS355** ALLISON USA Standing EGBJ (GLO): 18/03/2013 201302805 250 FAMILY Gloucestershire Smoke and electrical burning smell in the cockpit. Engines shut down and emergency declared. Slight electrical burning smell was noticed on completion of initial start up sequence during pre take-off checks. Smoke was then observed coming from the upper console on P1 side. Fire services assistance requested and emergency cut-off switch selected **AEROSPATIALE AS355** ALLISON USA 07/05/2013 Landing EGLD: Denham 201305010 250 FAMILY Nr2 engine running 50deg hotter than nr1 engine. Crack found on the outer combustion case near igniter plug housing. **AEROSPATIALE SA365** TURBOMECA, 26/03/2013 Initial climb Kyle of Lochalsh 201303418 **FRANCE** ARRIEL Just after take-off passing 500ft 'AUX hyd' caption illuminated. Illumination occurred just after undercarriage had completed travelling up. 'Aux hyd' switched to bypass and caption extinguished. Gear selected down normally and a/c returned. Fault traced to a micro switch on the landing gear nose leg-**AGUSTA A109** PRATT & WHITNEY EGSS (STN): 10/03/2013 201302440 Standing (USA) London/Stansted Other

Stand Confusion. CHROMA showed Agusta A109 on Stand 509 but ATC EFPS had shown Stand 511. Helicopter was parked on Stand 509.

Agusta A109 had arrived at Stansted earlier and had been due to return at 1335hrs but came back early at 1141hrs and parked on Stand 509. However, EFPS system shown the helicopter as being on Stand 511 and pilot was instructed to taxi via taxi lane F to the HAP. When helicopter was seen taxiing across Stand 509 it was initially thought that the pilot had taxied the wrong way down the dis-used runway and was told to hold position by the ground controller. On being queried the pilot stated that he had lifted from Stand 511. An airside OPs vehicle confirmed that he had actually been on Stand 509 and heading towards runway holding point V1 and not the HAP as instructed. Taxi instruction was amended and the helicopter departed without incident.

AGUSTA A109 PRATT & WHITNEY Initial climb EGKR (KRH): Redhill 25/02/2013 201302897 (USA)

A/c returned due to landing gear malfunction. Gear failed to retract.

Several attempts were made to retract the landing gear but no success. A/c landed safely. Engineers inspection found that the safety locking pin was not disengaging, preventing the lever from moving. The locking pin's disengagement is activated by the weight on wheels switch, which was found to be just on the cusp of activating. The switch rigging was adjusted to operate correctly. System tested, all satisfactory and a/c returned to service.

AGUSTA A109 PRATT & WHITNEY En-route EGVO (ODH): Odiham 29/04/2013 201304787 (CANADA) PW200 FAMILY An Agusta A109 infringed the Odiham ATZ (Class G) at 2000ft. No other a/c were affected by the infringement. PRATT & WHITNEY AGUSTA A109 16/05/2013 201305931 Cruise Brent Reservoir (CANADA) PW200 FAMILY Birdstrike to nose section of a/c. Minor damage caused. Damage inspected and engineering advice was sought. Decision made to continue with the return flight. BELL 206 ALLISON USA 11/05/2013 201305219 En-route EGGW (LTN): 250 FAMILY London/Luton Infringement of the Luton CTR (Class D) by a Bell 206 squawking 5031 at 1400ft. Pilot apologised. Standard separation maintained. The radar replay confirms that the a/c briefly entered the Luton CTR before being turned promptly by Farnborough LARS. Due to the short duration of this infringement, the prompt action taken by LARS and the fact that the pilot apologised, no further action is being taken. The pilots report indicates that he mistook Letchworth for Baldock BELL 206 04/05/2013 201305066 ALLISON USA Cruise En-route 250 FAMILY Reporter expressed concern regarding the non-publication of live VHF parachuting frequency 129.90. Reporter commented they would be contacting the relevant authorities to request that VHF frequency 129.90 is included on all aviation maps for the parachuting zone on the North shore of the Firth of Tay (Errol). **BELL 412** PRATT & WHITNEY Hovering EGOS : Shawbury 05/03/2013 201302364 (CANADA) PT-6 FAMILY Minor control restriction in cyclic. A/c returned. Force gradient spring adjusted EGTG (FZO): Bristol/Filton **BOLKOW BO105** ALLISON USA Cruise 26/03/2013 201303196 250 FAMILY A/c returned due to generator failure in the cruise. ECL actioned for under voltage and an uneventful landing was completed. Engineering investigation traced the fault to a sheared starter generator spline drive. Starter generator replaced and tested. A/c returned to service. BOLKOW BO105 ALLISON USA Scheduled EGTG (FZO): Bristol/Filton 27/03/2013 201303268 250 FAMILY maintenance Nr1 engine compressor found damaged during inspection. During inspection the engineer noticed a small 8mm bolt lying on the LH transmission decking. The bolt was identified as having come from the nr1 engine intake ring. An inspection of the engine intake revealed impact damage to the 1st stage compressor blades of the nr1 engine. A/c removed from service. Further in depth inspection found that all 16 blades on the 1st stage had been damaged but no damage had occurred to other stages or to the compressor casings or stator blades. The damage was within the blendable area and limits of the OEM so were blended and polished iaw OEM 72-30-00. Checked, tested and a/c released to service. **EUROCOPTER (EC145)** UNKNOWN Normal descent EGAA (BFS): 27/01/2013 201300727 Belfast/Aldergrove ATC callsign confusion between two fltnum 442s. The controller mistakenly instructed the wrong a/c to descend. **EUROCOPTER EC120** TURBOMECA, 14/05/2013 201305466 Landing Cullompton **FRANCE** ARRIUS Main rotor blade strike.

Landing at private site, gust of wind caused three rotor blade tips to contact tree branches.

	PRATT & WHITNEY (USA) Other	Hovering out of ground effect	EGSS (STN): London/Stansted	09/03/2013	201302513
Complete pilot comms and intercent Selection of emergency on CCS I	om failure. box caused ICS2 circuit breaker to	o trip. A/c recovered for e	ngineering assistance.		
		·			
EUROCOPTER EC135	TURBOMECA, FRANCE ARRIUS	Scheduled maintenance	EGBJ (GLO): Gloucestershire	07/03/2013	201302609
	t due incorrect date transferred fro to ensure accuracy between forec		<b>j</b> .		
UROCOPTER EC135	TURBOMECA, FRANCE ARRIUS	Initial climb	Strensham	11/03/2013	201302863
shortly after take-off the rotor bra ault traced to sticking rotor brak	ske caption illuminated. A/c returne e calliper microswitch.	ed to base.			
EUROCOPTER EC135	TURBOMECA, FRANCE ARRIUS	Scheduled maintenance	Staverton	25/03/2013	201303116
Overfly of maintenance. No has overflown 400hr servicinç	g by 12hrs. This is due to an error	in recording the next sch	eduled maintenance.		
UROCOPTER EC135	TURBOMECA, FRANCE ARRIUS	Standing : Engine(s) Start-up	Garth	03/04/2013	201303523
ngineering support on site confi	observed in column nr2 with no Trmed cause to be the T4 pyrometr	ric harness.			
UROCOPTER EC135	TURBOMECA, FRANCE ARRIUS	Landing	Other	29/04/2013	201304672
v/c, landing at a private site, becal bnormal changes to a/c attitude	ame enveloped in a dust cloud du felt through airframe or controls o				
Vc, landing at a private site, becaus No landing at a private site, becaus No further damage observed.	ame enveloped in a dust cloud du				
v/c, landing at a private site, becchormal changes to a/c attitude lo further damage observed.	ame enveloped in a dust cloud du felt through airframe or controls o TURBOMECA, FRANCE	n landing. Damaged site	dimensions approx 300m x 150	m. Paint damage to	underside of vertical fin
Vc, landing at a private site, becaubnormal changes to a/c attitude to further damage observed.  EUROCOPTER EC135  Green laser attack.	ame enveloped in a dust cloud du felt through airframe or controls o TURBOMECA, FRANCE	n landing. Damaged site	dimensions approx 300m x 150	m. Paint damage to	underside of vertical fin
v/c, landing at a private site, becaphormal changes to a/c attitude to further damage observed.  SUROCOPTER EC135  Green laser attack.  SUROCOPTER EC135  AN declared due to increased not ingineer report suggests suspect	ame enveloped in a dust cloud du felt through airframe or controls of TURBOMECA, FRANCE ARRIUS  PRATT & WHITNEY (CANADA)	Hovering  Cruise  rbox area and 'Rotor Bra	Overhead Sittingbourne  Seaton Delaval  ke' caption illumination. A/c set of the set of	m. Paint damage to  17/04/2013  05/05/2013  down in a field.	201304824 201304887
Vc, landing at a private site, becaphormal changes to a/c attitude to further damage observed.  EUROCOPTER EC135  Green laser attack.  EUROCOPTER EC135  PAN declared due to increased natingineer report suggests suspectingoing.	TURBOMECA, FRANCE ARRIUS  PRATT & WHITNEY (CANADA) PW200 FAMILY  poise levels coming from main gea	Hovering  Cruise  rbox area and 'Rotor Bra	Overhead Sittingbourne  Seaton Delaval  ke' caption illumination. A/c set of the set of	m. Paint damage to  17/04/2013  05/05/2013  down in a field.	201304824 201304887
Vc, landing at a private site, becaphormal changes to a/c attitude to further damage observed.  EUROCOPTER EC135  Breen laser attack.  EUROCOPTER EC135  PAN declared due to increased not ingineer report suggests suspectingoing.  EUROCOPTER EC135	TURBOMECA, FRANCE ARRIUS  PRATT & WHITNEY (CANADA) PW200 FAMILY  loise levels coming from main geal ted faulty brake cylinder. Rotor branches	Hovering  Cruise  rbox area and 'Rotor Braake deactivated, rotor bracked by the cruising level or altitude	Overhead Sittingbourne  Seaton Delaval  Ke' caption illumination. A/c set on the disc was ensured free. Transe	m. Paint damage to  17/04/2013  05/05/2013  down in a field.	201304824  201304887  defects list. Investigation
EUROCOPTER EC135  PAN declared due to increased neighboring.  Pandeclared due to increased neighboring.  EUROCOPTER EC135  EUROCOPTER EC135  EUROCOPTER EC135  EUROCOPTER EC135	TURBOMECA, FRANCE ARRIUS  PRATT & WHITNEY (CANADA) PW200 FAMILY  coise levels coming from main geated faulty brake cylinder. Rotor bracket	Hovering  Cruise  rbox area and 'Rotor Braake deactivated, rotor bracked by the cruising level or altitude	Overhead Sittingbourne  Seaton Delaval  Ke' caption illumination. A/c set on the disc was ensured free. Transe	m. Paint damage to  17/04/2013  05/05/2013  down in a field.	201304824  201304887  defects list. Investigation

EUROCOPTER EC135	TURBOMECA, FRANCE ARRIUS	En-route	Overhead Rushden	08/05/2013	201305403
Laser attack.					
EUROCOPTER EC135	TURBOMECA, FRANCE ARRIUS	Cruise	Overhead Newcastle Upon Tyne	08/05/2013	201305488
Green laser attack.					
EUROCOPTER EC135	PRATT & WHITNEY (CANADA) PW200 FAMILY	Hovering	Unknown	21/05/2013	201305757
	and RRPM indication showed zero dance with FRCs. A/c declared un		nd placed unserviceable. Engine	ering informed.	
EUROCOPTER EC135	PRATT & WHITNEY (CANADA) PW200 FAMILY	Hovering/transitio n from hover to forward flight	EGBJ (GLO): Gloucestershire	29/04/2013	201304612
	and EC135 and an inhound C182	R/W27. C182 initiated a m	nissed approach		
JK AIRPROX 2013/026 - Outbou	ind EC133 and an inbound C102		посси арргоаот.		
UK AIRPROX 2013/026 - Outbou	PRATT & WHITNEY (USA) Other	Scheduled maintenance	Husbands Bosworth	04/03/2013	201302328
EUROCOPTER EC135  Contaminated fuel. Particles of runce addition, smaller particles had and been replaced, which was sit investigate and have made recomparts.	PRATT & WHITNEY (USA) Other  abber shavings were found in the got through the filter and into the futuated 'downstream' of the main demendations for a change to SOP	Scheduled maintenance gauze filter of the fuel systuel sample. The fuel farm ifferential pressure filter. A	Husbands Bosworth  tem during weekly check. If at the establishment had been row full the control of the contro	recently cleaned ar maintenance com	nd a short length of hos pany were requested t
EUROCOPTER EC135  Contaminated fuel. Particles of ruin addition, smaller particles had had been replaced, which was sit	PRATT & WHITNEY (USA) Other  abber shavings were found in the got through the filter and into the futuated 'downstream' of the main demendations for a change to SOP	Scheduled maintenance gauze filter of the fuel systuel sample. The fuel farm ifferential pressure filter. A	Husbands Bosworth  tem during weekly check. If at the establishment had been row full the control of the contro	recently cleaned ar maintenance com	nd a short length of hos pany were requested t
EUROCOPTER EC135  Contaminated fuel. Particles of ruin addition, smaller particles had an addition, smaller particles had shad been replaced, which was sit investigate and have made recompose replacements that occur in t	PRATT & WHITNEY (USA) Other  sibber shavings were found in the got through the filter and into the livated 'downstream' of the main d anmendations for a change to SOP that area.  PRATT & WHITNEY (USA)	Scheduled maintenance gauze filter of the fuel syst uel sample. The fuel farm ifferential pressure filter. As to include daily, rather t  Cruise  s. Non essential electrics	Husbands Bosworth  tem during weekly check. If at the establishment had been raction for the fuel than weekly checks, to be carried  EGTC: Cranfield  isolated and a/c diverted.	recently cleaned ar maintenance com out for a two weel	nd a short length of hos pany were requested t k period following any
EUROCOPTER EC135  Contaminated fuel. Particles of ru in addition, smaller particles had had been replaced, which was sit investigate and have made recompose replacements that occur in the EUROCOPTER EC135  Flight crew and passengers beca Fault traced to a chaffed and burn	PRATT & WHITNEY (USA) Other  abber shavings were found in the got through the filter and into the functed 'downstream' of the main domendations for a change to SOP that area.  PRATT & WHITNEY (USA) Other  me aware of acrid electrical fumes	Scheduled maintenance gauze filter of the fuel syst uel sample. The fuel farm ifferential pressure filter. As to include daily, rather t  Cruise  s. Non essential electrics	Husbands Bosworth  tem during weekly check. If at the establishment had been raction for the fuel than weekly checks, to be carried  EGTC: Cranfield  isolated and a/c diverted.	recently cleaned ar maintenance com out for a two weel	nd a short length of hos pany were requested t k period following any
EUROCOPTER EC135  Contaminated fuel. Particles of run addition, smaller particles had an addition, smaller particles had need been replaced, which was sit investigate and have made recomnose replacements that occur in the EUROCOPTER EC135  Flight crew and passengers becafault traced to a chaffed and burne EUROCOPTER EC135  A/c returned due to XMSN transman	PRATT & WHITNEY (USA) Other  sibber shavings were found in the got through the filter and into the futuated 'downstream' of the main domendations for a change to SOP that area.  PRATT & WHITNEY (USA) Other  me aware of acrid electrical fument through electrical cable supplying the	Scheduled maintenance gauze filter of the fuel syst uel sample. The fuel farm ifferential pressure filter. A s to include daily, rather t  Cruise  S. Non essential electrics ag instrument lighting thro	Husbands Bosworth  tem during weekly check. I at the establishment had been row for fuel tanks inspected. The fuel than weekly checks, to be carried  EGTC: Cranfield  isolated and a/c diverted. ugh vibration.  EGNO: Warton	recently cleaned ar maintenance com out for a two weel 09/05/2013	nd a short length of hos pany were requested t k period following any 201305179
EUROCOPTER EC135  Contaminated fuel. Particles of ruin addition, smaller particles had a had been replaced, which was sit investigate and have made recombose replacements that occur in the EUROCOPTER EC135  Flight crew and passengers because fault traced to a chaffed and burne EUROCOPTER EC135  A/c returned due to XMSN transmall other indications appeared not	PRATT & WHITNEY (USA) Other  Abber shavings were found in the got through the filter and into the guated 'downstream' of the main domendations for a change to SOP that area.  PRATT & WHITNEY (USA) Other  TURBOMECA, FRANCE ARRIUS  hission chip light on departure.	Scheduled maintenance gauze filter of the fuel syst uel sample. The fuel farm ifferential pressure filter. A s to include daily, rather t  Cruise  S. Non essential electrics ag instrument lighting thro	Husbands Bosworth  tem during weekly check. I at the establishment had been row for fuel tanks inspected. The fuel than weekly checks, to be carried  EGTC: Cranfield  isolated and a/c diverted. ugh vibration.  EGNO: Warton	recently cleaned ar maintenance com out for a two weel 09/05/2013	nd a short length of hos pany were requested t k period following any 201305179
EUROCOPTER EC135  Contaminated fuel. Particles of ruin addition, smaller particles had had been replaced, which was sit investigate and have made recombose replacements that occur in the EUROCOPTER EC135  Flight crew and passengers because fault traced to a chaffed and burne EUROCOPTER EC135  A/c returned due to XMSN transmall other indications appeared not EUROCOPTER EC155	PRATT & WHITNEY (USA) Other  abber shavings were found in the of got through the filter and into the frusted 'downstream' of the main of mendations for a change to SOP that area.  PRATT & WHITNEY (USA) Other  TURBOMECA, FRANCE ARRIUS  ARRIUS  ARRIUS  ARRIUS  ARRIUS  ARRIUS  CAS by climbing straight ahead to	Scheduled maintenance gauze filter of the fuel systing sample. The fuel farm ifferential pressure filter. As to include daily, rather the cruise  Cruise  S. Non essential electrics againstrument lighting through Initial climb  Initial climb  Climb to cruising level or altitude	Husbands Bosworth  tem during weekly check. I at the establishment had been row for fuel tanks inspected. The fuel than weekly checks, to be carried  EGTC: Cranfield  isolated and a/c diverted. ugh vibration.  EGNO: Warton  meering advice sought.  EGSH (NWI): Norwich	18/03/2013	and a short length of hos pany were requested to period following any 201305179  201302443  201302821

MD HELICOPTER 902	PRATT & WHITNEY (CANADA) PW200 FAMILY	Cruise	Near Harpenden	03/04/2013	201303439
PAN declared and emergency land Vc landed safely on a golf course init was isolated by pulling the C/E eplaced.	and engineering assistance sou	ght. It was suspected tha			
MD HELICOPTER MD900	PRATT & WHITNEY (USA) Other	Standing : Engine(s) Not Operating	Royal London Hospital	16/02/2013	201302044
Plastic bag melted around heater valuring daily check, plastic bubble aware of the incident and need to equipment valises for compliance	wrap used for keeping patients wensure that items of medical equ	ipment are correctly stor	wed. The organisation is in the pr	ocess of reviewing	all 'carry-on' medical
MD HELICOPTER MD900	PRATT & WHITNEY (CANADA) PW200 FAMILY	Approach - holding	United Kingdom-Worksop	02/03/2013	201302943
Electronic engine control (EEC) fai Vc in orbit at 300ft to check for lar effect. A/c returned using manual t	nding site. EEC failure warning. F			neters. EEC reset p	rocedure carried had no
MD HELICOPTER MD900	PRATT & WHITNEY (USA) Other	Scheduled maintenance	EGBJ (GLO): Gloucestershire	01/03/2013	201303004
Main rotor drive ring found cracked	d during daily inspection.				
Vc inspected for installation issue	or other factors which could have	e caused the failure. No	ne found. Drive ring replaced law	CSP-900RMM-2.	
Vc inspected for installation issue	PRATT & WHITNEY (CANADA) PW200 FAMILY	e caused the failure. No  Scheduled  maintenance	ne found. Drive ring replaced law  EGBJ (GLO): Gloucestershire	01/03/2013	201303005
	PRATT & WHITNEY (CANADA) PW200 FAMILY  ECU) vapour hoses found detach	Scheduled maintenance	EGBJ (GLO): Gloucestershire  ng Unit (FMU) vapour shroud cov	<b>01/03/2013</b> Pers.	
MD HELICOPTER MD900  Nr1 and nr2 Engine Control Unit (E	PRATT & WHITNEY (CANADA) PW200 FAMILY  ECU) vapour hoses found detach	Scheduled maintenance	EGBJ (GLO): Gloucestershire  ng Unit (FMU) vapour shroud cov	<b>01/03/2013</b> Pers.	
MD HELICOPTER MD900  Nr1 and nr2 Engine Control Unit (E  N/c undergoing daily inspection. N	PRATT & WHITNEY (CANADA) PW200 FAMILY  ECU) vapour hoses found detach o visible signs of wire locking use  PRATT & WHITNEY (USA) Other  search and rescue mission. eeing an object falling from a/c. N	Scheduled maintenance  ned from the Fuel Meterined to retain the hoses to  En-route: Other	EGBJ (GLO): Gloucestershire  Ing Unit (FMU) vapour shroud cover the FMU being fitted. Omission to the FMU being fitted.	01/03/2013  ers. raced to previous m 31/03/2013	naintenance organisation 201303461
MD HELICOPTER MD900  Nr1 and nr2 Engine Control Unit (EVC undergoing daily inspection. Now MD HELICOPTER MD900  Report of object falling from a/c on A member of the public reported so	PRATT & WHITNEY (CANADA) PW200 FAMILY  ECU) vapour hoses found detach o visible signs of wire locking use  PRATT & WHITNEY (USA) Other  search and rescue mission. eeing an object falling from a/c. N	Scheduled maintenance  ned from the Fuel Meterined to retain the hoses to  En-route: Other	EGBJ (GLO): Gloucestershire  Ing Unit (FMU) vapour shroud cover the FMU being fitted. Omission to the FMU being fitted.	01/03/2013  ers. raced to previous m 31/03/2013	naintenance organisation 201303461
MD HELICOPTER MD900  Nr1 and nr2 Engine Control Unit (EVc undergoing daily inspection. Nr  MD HELICOPTER MD900  Report of object falling from a/c on a member of the public reported surea searched with nothing found.	PRATT & WHITNEY (CANADA) PW200 FAMILY  ECU) vapour hoses found detach o visible signs of wire locking use  PRATT & WHITNEY (USA) Other  search and rescue mission. eeing an object falling from a/c. N It should be noted that at the tim  PRATT & WHITNEY (USA) Other  pund not correctly secured. he pilot informed the engineer that up ring. Subsequent inspections jations found that at a different by	Scheduled maintenance  med from the Fuel Meterined to retain the hoses to  En-route: Other  No indications or instrummenther was gliding active  Standing  at there appeared to be a found the fuel filler neckase, the fuel nozzle used	EGBJ (GLO): Gloucestershire  Ing Unit (FMU) vapour shroud cover the FMU being fitted. Omission to the FMU being seen. Precautionary vity and flocks of birds in the area to the FMU (NHT): Northolt in the FMU (NHT): Northolt in the main fuel tank joint correctly and by the refuelling contractor had	01/03/2013  ers. raced to previous m 31/03/2013  landing carried out 04/04/2013  e fuel filler neck cal ssembled with no s a large diameter fla	201303461  201303461  . A/c and surrounding  201303604  p lanyard. This was signs of damage. New attened end that could
MD HELICOPTER MD900  Note and nr2 Engine Control Unit (ENC undergoing daily inspection. Note and the public reported so area searched with nothing found.  MD HELICOPTER MD900  After flight, the fuel filler cap was for the fuel cap back to be the fuel cap back to back up ring fitted. Further investignation in the pack up ring fitted. Further investignation the back up ring during refue the fuel cap during refue the back up ring during refue the fuel cap during refue the pack up ring during refue the fuel cap back up ring fitted. Further investignation the back up ring during refue the fuel cap during refuer the fuel c	PRATT & WHITNEY (CANADA) PW200 FAMILY  ECU) vapour hoses found detach o visible signs of wire locking use  PRATT & WHITNEY (USA) Other  search and rescue mission. eeing an object falling from a/c. N It should be noted that at the tim  PRATT & WHITNEY (USA) Other  pund not correctly secured. he pilot informed the engineer that up ring. Subsequent inspections jations found that at a different by	Scheduled maintenance  med from the Fuel Meterined to retain the hoses to  En-route: Other  No indications or instrummenther was gliding active  Standing  at there appeared to be a found the fuel filler neckase, the fuel nozzle used	EGBJ (GLO): Gloucestershire  Ing Unit (FMU) vapour shroud cover the FMU being fitted. Omission to the FMU being seen. Precautionary vity and flocks of birds in the area to the FMU (NHT): Northolt in the FMU (NHT): Northolt in the main fuel tank joint correctly and by the refuelling contractor had	01/03/2013  ers. raced to previous m 31/03/2013  landing carried out 04/04/2013  e fuel filler neck cal ssembled with no s a large diameter fla	201303461  . A/c and surrounding  201303604  p lanyard. This was signs of damage. New attened end that could
MD HELICOPTER MD900  Note and nr2 Engine Control Unit (ENC undergoing daily inspection. Note and the public reported so area searched with nothing found.  MD HELICOPTER MD900  After flight, the fuel filler cap was for the fuel anding and shutting down, the confirmed to be the fuel cap back to pack up ring fitted. Further investigatch the back up ring during refuerters. Fleet check initiated.	PRATT & WHITNEY (CANADA) PW200 FAMILY  ECU) vapour hoses found detach o visible signs of wire locking use  PRATT & WHITNEY (USA) Other  search and rescue mission. eeing an object falling from a/c. N It should be noted that at the tim  PRATT & WHITNEY (USA) Other  Dund not correctly secured. he pilot informed the engineer that up ring. Subsequent inspections jations found that at a different beling. The operator will review re  PRATT & WHITNEY (USA)	Scheduled maintenance  led from the Fuel Meterined to retain the hoses to  En-route: Other  No indications or instrume there was gliding active  Standing  at there appeared to be a found the fuel filler neck ase, the fuel nozzle used fuelling procedures at the	EGBJ (GLO): Gloucestershire  Ing Unit (FMU) vapour shroud cover the FMU being fitted. Omission to the FMU being seen. Precautionary vity and flocks of birds in the area to the FMU (NHT): Northolt in the main fuel tank joint correctly and by the refuelling contractor had is base and will issue a Flight Sa	01/03/2013  ers. raced to previous m 31/03/2013  landing carried out 04/04/2013  e fuel filler neck callssembled with no salarge diameter flatety Circular to bring	201303461  201303461  . A/c and surrounding  201303604  p lanyard. This was signs of damage. New attened end that could g to the attention of their

MD HELICOPTER MD900	PRATT & WHITNEY (USA) Other	Scheduled maintenance	EGWU (NHT): Northolt	08/05/2013	201305067
Seal had been replaced Jan 201	be debonding from its backing plat 13 during the a/c annual service an and associated items and area vis er for analysis.	d the a/c had flown 93hrs			
ROBINSON R44	LYCOMING 540 FAMILY	Cruise	SAM	19/05/2013	201305612
	n CTR (Class D) by an R44 squaw outhampton ATC to advise they had			lled London FIS inste	ead.
ROBINSON R44	LYCOMING 540 FAMILY	Cruise	EGNM (LBA): LEEDS BRADFORD	01/05/2013	201304708
Infringement of the Leeds Bradfo	ord CTA (Class D) by an R44 at 34	.00ft. Pilot was informed o	f the infringement. No other a/	c were in the area.	
ROBINSON R44	LYCOMING 540 FAMILY	Standing : Engine(s) Operating	EGLD : Denham	02/05/2013	201304860
UK Reportable Accident: During	start up the a/c rotated and ended	up coming to rest on the	tail boom. One POB, no injurie	es. Subject to AAIB A	AARF investigation.
SIKORSKY S76	TURBOMECA, FRANCE ARRIEL	Hovering - landing	Caister Gas Platform	01/03/2013	201302200
Nr2 engine chip caution illumina Upon landing the chip caution ill carried out with same result. En A/c returned with no further prob	uminated EOP carried out and cau gineering were contacted and an ir	tion cleared. Upon lifting ispection of the chip detection	nto hover for next sector, the otor and mag plugs was carried	chip illuminated agair d out along with leak	n. A/c landed and EOP checks and ground runs.
SIKORSKY S76	TURBOMECA, FRANCE ARRIEL	Take-off	Unknown	21/05/2013	201305167
	e a/c had been knowingly operated n with a/c weight at 10988lb when				
SIKORSKY S76	TURBOMECA, FRANCE ARRIEL	Intermediate approach	EGLD : Denham	23/05/2013	201305867

 $Incident: Tail\ rotor\ control\ malfunction.\ helicopter\ carried\ out\ running\ landing.\ Subject\ to\ AAIB\ AARF\ investigation.$ 

# **OCCURRENCE LISTING** Aircraft Below 5700kg OCCURRENCES RECORDED BETWEEN 01 May 2013 and 31May 2013

## **OTHER**

CAMERON C90	OTHER (Not Applicable)	Landing	Croyland Park	05/05/2013	201305162
Balloon impacted and damage	d a small lamp post on landing. N	No injuries to a/c occupants	and no damage caused to balloc	on.	
CAMERON Z350	OTHER	Approach	Wolfhill	07/05/2013	201305216
	ilot made precautionary landing. I and no damage to the balloon.	Manufacturer is currently in	vestigating.		
GLASER DIRKS DG808C		En-route	Aviemore - Spey Valley	30/04/2013	201304762
UK AIRPROX 2013/027 - Milita	ary a/c and a Glider at 250 agl Sp	pey Valley, 4nm South West	Aviemore.		
GLASER DIRKS DG1000	UNKNOWN	Cruise	Reading	26/04/2013	201304599
A/c avoiding showers enroute.	ss A) by a DG 1000 glider at 400	UIT.			
GLASFLUGEL H201	OTHER	En-route - Other	Tibenham Airfield	05/05/2013	201305104
	sconnected resulting in wing flutte			00/05/2042	204205442
GROB G102	UNKNOWN	Level- off/touchdown	Shenington Gliding Club	06/05/2013	201305110
UK reportable Accident: A/c bo Damage to cockpit and wings.	unced on landing. One POB no i	njuries. Investigation delega	ated to BGA.		
GROB G103	OTHER (N/A )	Take-off - winch- launch: Other	Seighford Airfield	17/02/2013	201304446

Partial loss of glider canopy on winch launch.

The flight followed an uneventful first flight. About 2/3 into the winch launch, a loud crack was heard and the canopy was seen to detach and strike the tail. The pilot immediately released the cable and flew a cautious abbreviated circuit and landed towards the upwind end of the airfield. A thorough investigation has been carried out and the cause has been determined as inconclusive as no direct evidence can be found for the cause of the failure. Maintenance, prior damage and operational factors have all been reasonably excluded.

SCHEIBE SF25	BOMBARDIER ROTAX 912	En-route	Winchester	11/04/2013	201303917
nfringement of the Southampton C ilot error acknowledged. Poor visi		ft. Pilot realised error	and turned and descended to va	cate the zone.	
SCHEMPP HIRTH VENTUS B	OTHER	Level- off/touchdown	Near Penyclawdd Fisheries	08/05/2013	201305096
JK Reportable Accident: Landed in	field, through hedge and came to	rest on road. One Po	OB no injuries. Investigation dele	gated to BGA.	
SCHLEICHER ASH25	OTHER (Not Applicable)	Thermal lift	M40	06/05/2013	201305011
JK AIRPROX 2013/031 - Schleich	er ASH25 glider and a BE95.				
SCHLEICHER ASW15	OTHER	En-route	Ousbydale, Pennines	10/05/2013	201305575
UK Reportable Accident. During hil	I soaring a/c crashed. One POB n	o injuries. Investigatio	on delegated to BGA.		
SCHLEICHER ASW20	OTHER	Unknown	North Devon Coast	26/04/2013	201304749
UK Reportable Accident: Glider dito Glider lost at sea.	ched in sea. One POB no injuries.	Investigation delegat	ed to BGA.		
SCHLEICHER ASW27	OTHER (Not applicable)	Unknown	Tibenham	12/05/2013	201305359
UK AIRPROX 2013/033 - Schleiche	er ASW27 and an unknown a/c, W	est of Tibenham Airfi/	eld.		
SCHLEICHER ASW27	OTHER (not applicable)	En-route	En-route	20/04/2013	201304379
UK AIRPROX 2013/020 - ASW27 (	glider and a PA34 at 4300ft.				
SCHLEICHER K7	OTHER (N/A)	Level- off/touchdown	Dartmoor Gliding Club	27/04/2013	201304736
UK Reportable Accident: A/c suffer	ed a heavy landing and impacted	a fence. One POB. n	o injuries Damage to RH wing S	Subject to BGA inves	tigation

# **OCCURRENCE LISTING**

# Aircraft Below 5700kg

## OCCURRENCES RECORDED BETWEEN 01 May 2013 and 31May 2013

#### **ABBREVIATIONS**

AAIB Air Accidents Investigation Branch

AAL Above aerodrome level

**AARF** Aircraft Accident Report Form

A/c Aircraft (or a/c) AD Airworthiness Directive

**ADELT** Automatically Deployed Emergency Locator Transmitter

**AFS** Airport Fire Service

AIP Aeronautical Information Publication

A/P Autopilot

ASI Airspeed indicator

BS **Basic Service** 

Controlled Airspace Intrusion Tool CAIT

CAS Controlled Airspace DS EFIS

Deconfliction Service
Electronic Flight Instrument System

FIS Flight Information Service **FRC** Flight Reference Card

GASIL General Aviation Safety Information Leaflet **IHUMS** Integrated Health and Usage Monitoring System

Kts Knots

LACC London Area Control Centre **London Terminal Control Centre** LTCC

LH Left-hand

MACC Manchester Area Control Centre

MGB Main gearbox Main Landing Gear MLG

MPD Maintenance planning document or Mandatory Permit Directive

MOR Mandatory Occurrence Report

Nose landing gear NLG Nr1 Number 1 NM **Nautical Miles** Prestwick Centre PC **PCB** Printed Circuit Board POB Persons on board Right-hand RH RT Radio Telephony

R/W Runway

**ScACC** Scottish Area Control Centre Standard Operating Procedure SOP Temporary Danger Area TDA

VATDA Volcanic Ash Temporary Danger Area

**VCR** Visual Control Room (Tower)

If another abbreviation that you do not understand appears in the listing please email sdd@caa.co.uk for a definition, or try an internet search engine such as Google.