# Safety Regulation Group Safety Information and Data Department



# Follow-up Action on Occurrence Report

ACCIDENT TO DHC-8-402 (Q400), G-JEDW, AT LEEDS BRADFORD AIRPORT ON 20 OCTOBER 2005 (HEAVY LANDING DURING CONTINUATION TRAINING)

CAA FACTOR NUMBER : F36/2006

FACTOR PUBLICATION DATE : 10 October 2006

OPERATOR : flybe

CAA OCCURRENCE NUMBER : 2005/08676

AAIB REPORT : Bulletin 9/2006

**SYNOPSIS** 

(From AAIB Report)

The aircraft was conducting a practice CAT II ILS approach to Runway 32 at Leeds Bradford International Airport in VMC. Contrary to company standard operating procedures, the co-pilot flew the approach and the landing. At a height of approximately 80 ft, the co-pilot retarded both power levers, resulting in a high rate of descent. Both pilots applied power and the co-pilot flared positively in an attempt to reduce this rate of descent. In doing so, the aircraft was pitched-up to an angle sufficient to cause the underside of the rear fuselage to contact the ground. Damage was confined to the composite fairing covering the 'runway touched' sensor. There were no injuries. Although not a cause of the incident, the investigation revealed that the heading selectors for the commander and co-plot operated independently, resulting in a temporary deviation from the ATC assigned heading. This was not noticed immediately by the non-handling commander. Two safety recommendations are made.

#### **FOLLOW UP ACTION**

The two Safety Recommendations, made by the AAIB following their investigation, are reproduced below, together with the CAA's responses.

### Recommendation 2006-49

It is recommended that the aircraft operator, Flybe, expedite the reconfiguring of the heading selector systems on their DHC-8-400 (Q400) aircraft that do not have coupled heading selectors, such that operation of ether heading selector results in an identical selection being presented on both the commander's and co-pilot's flight instruments.

#### **CAA Response**

This Recommendation is not addressed to the CAA.

**CAA Status - Closed** 

This publication provides the initial CAA response to each Safety Recommendation made by the Air Accidents Investigation Branch, Department of Transport. **Status 'CLOSED' or 'OPEN' indicates completion or not of all actions judged appropriate by the CAA in response to the Recommendation.** It is published by the Safety Investigation and Data Department, Safety Regulation Group, Givil Aviation Authority, Aviation House, Gatwick Airport South, West Sussex, RH6 0YR. Tel: 01293 573220 Fax: 01293 573972 Telex: 878753.

The Civil Aviation Authority should ensure that co-pilots of Bombardier DHC-8-400 series aircraft operated by Flybe, receive training and practice n landing the aircraft from a Category II ILS approach.

## **CAA Response**

The CAA accepts this Recommendation. The CAA is working closely with the operator, Flybe, and will ensure that co-pilots of Bombardier DHC-8-400 series aircraft will receive training and practice in landing the aircraft from a Category II ILS approach.

**CAA Status - Open**