

Civil Aviation Authority

EMERGENCY MANDATORY PERMIT DIRECTIVE



Number: 2012-004-E Issue date: 24 October 2012

In accordance with 22(1) of Air Navigation Order 2009 as amended the following action required by this Mandatory Permit Directive (MPD) is mandatory for applicable aircraft registered in the United Kingdom operating on a UK CAA Permit to Fly.

registered in the United Kingdom operating on a UK CAA Permit to Fly.				
Type Approval Holder's Name:		Type/Model Designation(s):		
Yeoman Light Aircraft Company Limited		Dynamic WT9-UK		
Title:	Fuel Cock Lever Inspection / Repair			
Manufacturer:	Yeoman Light Aircraft Company Limited			
Applicability:	Dynamic WT9-UK Serial Numbers DY135-DY239 inclusive.			
Reason:	Following service experience and a review by Yeoman Light Aircraft Company Limited, it has been identified that a potential failure mode exists for some early serial WT9-UK Dynamics in which the fuel cock lever may depart from the main body of the fuel cock, rendering the use of the fuel cock impossible.			
Effective Date:	24 October 2012			
Compliance/Action:	Within five flying hours of the effective date of this MPD, inspect the red fuel cock lever for its attachment in the fuel cock body and repair as necessary, in accordance with YLAC-SB-WT09-002-008.			
	This inspection (with remedial action if necessary) must be repeated at each 100h service.			
	Documentation			
	any work completed i	e should be made describing the inspection and n the aircraft logbook. The name, date and on who carried out the work should be included.		
ENSURE COMPLIANCE WITH THIS MPD IS RECORDED IN THE AIRCRAFT LOGBOOK				
Reference Publications:	Yeoman Light Aircraft Company Limited Service Bulletin YLAC-SB-WT09-002-008.			

Remarks:	1.	requirement.	
	2.		
	Tel	: +44 (0)1293 573726	Fax: +44 (0)1293 573976
	E-r	E-mail: department.certification@caa.co.uk	