

(I) Bell 212 Series Helicopters

I Additional Airworthiness Directives

1.1 001-06-99

Applicable to Bell 212 helicopters Serial Nos. 30501 through 31311 and 35001 through 35102 fitted with servo actuator Part No. 212-076-004-All (HR Part No. 41000570) that has been repaired or overhauled.

Compliance is required prior to the issue of a UK Certificate of Airworthiness from the effective date of this Directive which is 5 July 1999.

Inspect the servo actuator for unauthorized actuating lever assemblies in accordance with Alert Service Bulletin 212-98-103. Failure of the servo actuator could cause loss of control and possible loss of the helicopter.