

(2) De Havilland DH89 Rapide Series Aircraft

UK National Airworthiness Directives previously published in CAP 476 – Mandatory Aircraft Modifications and Inspections Summary

CAA AD No: 2735 PRE 80

Associated Material: Rapide Mod. 1(Dominie Mod. 65)

Description: Introduction of a screen on the windscreen wiper to eliminate compass interference.

Applicability – Compliance – Requirement

As an alternative to this modification a cockpit notice must be fitted, restricting the use of the wiper to the period during take off and landing.

CAA AD No: 2736 PRE 80

Associated Material: Rapide Mod. 2(Dominie Mod. 63)

Description: Anti-vibration strut on mainplane bracing –improved attachment of clip.

Applicability – Compliance – Requirement

-

CAA AD No: 2737 PRE 80

Associated Material: Rapide Mod. 5 (Dominie Mod. 69)

Description: Introduction of fuel drain pipe from induction manifold.

Applicability – Compliance – Requirement

To be embodied with Gipsy Mod. No. 1152.

CAA AD No: 2738 PRE 80

Associated Material: Rapide Mod. 9

Description: Introduction of Battery Master Switch.

Applicability – Compliance – Requirement

BEA Mod. E-5-4 is an acceptable alternative.

CAA AD No: 2739 PRE 80

Associated Material: Rapide Mod. 10

Description: Introduction of fuse in negative lead to radio.

Applicability – Compliance – Requirement

-

CAA AD No: 2740 PRE 80

Associated Material: Rapide Mod. 15

Description: To introduce bracing for rear diagonal struts and strengthened undercarriage radius rods.

Applicability – Compliance – Requirement

Applicable immediately on Rapide Series 4 or Rapide Series 5 aircraft.