SAFETY REGULATION GROUP

Aviation House Gatwick Airport South West Sussex RH6 0YR **UNITED KINGDOM**

Direct Dial Direct Fax

+44(0)1293 573239 +44(0)1293 573993

Switchboard Fax Telev

+44(0)1293 567171 +44(0)1293 573999

878753



Our ref 9/97/CtAw/314

30 March 1995

LETTER TO OWNERS/OPERATORS NO 1431 AIRCRAFT FIRE EXTINGUISHERS, SMOKE DETECTORS AND OXYGEN SYSTEM **EQUIPMENT SERVICED BY TEC-AIR**

The Civil Aviation Authority have been advised by the FAA that oxygen system equipment and aircraft fire extinguishers and smoke detectors serviced by

> Tec-Air Services Inc 2-10 Railroad Avenue East Northport NY 11731-1795

may not be airworthy.

Tec-Air have FAA repair station approval reference MAIR 315K and were previously accepted by JAA. JAA acceptance has now been withdrawn.

Please be advised that all equipment maintained by Tec-Air should be checked to confirm that all maintenance activities have been properly carried out. Equipment should be checked as soon as reasonably practicable and appropriate action taken should the equipment fail to meet an airworthiness standard.

If any discrepancies are found they should be reported through the Mandatory Occurrence Reporting system.

DJVLEWIS

Aircraft Maintenance Approvals