

(2) Beagle A.109 Aircraft

UK National Airworthiness Directives previously published in CAP 476 – Mandatory Aircraft Modifications and Inspections Summary

CAA AD No: 2422 PRE 80

Associated Material: Mod A.105

Description: Introduction of cooling duct for starboard magneto.

Applicability – Compliance – Requirement

Should have been embodied by 1 January 1964. Beagle Service Bulletin No. A.5 refers.

CAA AD No: 2423 PRE 80

Associated Material: Mod A.118

Description: Introduction of increased strength door hinge bearings.

Applicability – Compliance – Requirement

Should have been embodied by 1 January 1964. Beagle Service Bulletin No. A.5 refers.

CAA AD No: 2424 PRE 80

Associated Material: Mod A.140

Description: Introduction of revised door catch.

Applicability – Compliance – Requirement

Should have been embodied by 1 March 1964. Beagle Service Bulletin No. A.5 and Supplement refer.

CAA AD No: 2425 PRE 80

Associated Material: Mod A.182

Description: Fuel and Oil vent restriction requirement for A.C. lightweight diaphragm fuel pumps.

Applicability – Compliance – Requirement

Should have been embodied by 1 September 1964. Beagle Service Bulletin No. A.10 refers.

CAA AD No: 2426 PRE 80

Associated Material: SB No. A14

Description: Replacement of toxic type fire extinguishers.

Applicability – Compliance – Requirement

Should have been embodied by 30 September 1965. Modification No. 4179 refers.