

(2) Permali Group – Horden Richmond Wooden Fixed Pitch Propellers

UK National Airworthiness Directives previously published in CAP 476 – Mandatory Aircraft Modifications and Inspections Summary

CAA AD No: 2219 PRE 80

Associated Material: –

Description: Permali Group – Horden Richmond wooden fixed pitch propellers.

Applicability – Compliance – Requirement

Any propellers which have protecting sheathing in accordance with Modification SK504 must be withdrawn from service within a period not to exceed 50 hours flying since embodiment of this type of sheathing. The affected propellers have the letter 'M' after the drawing number stamped on the side of the boss. Subsequently these propellers should be resheathed by the manufacturer in accordance with Modification HR 1811, or HR 1812 or HR 1813.