(2) Rolls Royce Gem Series Engines

UK National Airworthiness Directives previously published in CAP 476 – Mandatory Aircraft Modifications and Inspections Summary

CAA AD No: 006-08-92 Associated Material: SB 73-24

Description: Engine Fuel and Control – Hydromechanical fuel flow control unit –

Inspection for fuel leakage and replacement of packing (sealing ring) and

back-up retaining ring.

Applicability - Compliance - Requirement

Applicable to Gem Mk 530 and 531 engines fitted on Westland 30 helicopters. Compliance required as detailed in Service Bulletin.