

(2) ARV Aviation ARV 1 Super 2 Aircraft

UK National Airworthiness Directives previously published in CAP 476 – Mandatory Aircraft Modifications and Inspections Summary

CAA AD No: 010-08-86

Associated Material: Maintenance Manual

Description: Mandatory Fatigue Lives

Applicability – Compliance – Requirement

The fatigue lives listed in Chapter 4 of the Maintenance Manual are mandatory for aircraft on the United Kingdom Register.

CAA AD No: 025-05-87

Associated Material: ARV-SB-002

Description: Hewland AE75C Aero Engine – Loctiting carburetor bellmouth screws and wirelocking carburetor heat box retaining screws

Applicability – Compliance – Requirement

Applicable to aircraft as detailed in Service Bulletin. Compliance required as detailed in Service Bulletin.

CAA AD No: 001-11-87

Associated Material: ARV-SB-008

Description: Hewland AE75C Engine – Propeller shaft

Applicability – Compliance – Requirement

Applicable to all aircraft fitted with Hewland AE75C engine gearboxes. Compliance required as detailed in Service Bulletin.

CAA AD No: 015-11-87

Associated Material: ARV-SB-007

Description: Damage to rudder pedals

Applicability – Compliance – Requirement

Applicable to aircraft up to and including Constructors No 024. Compliance required as detailed in Service Bulletin.

CAA AD No: 007-03-89

Associated Material: ARV-SB-012

Description: Cracks under the bearing sleeve on noseleg downtube

Applicability – Compliance – Requirement

Applicable to aircraft Constructors Nos. 001, 004K, 005K, 006K, 007K, 009K, 011, 012, 013, 017, 019 and 021. Compliance required as detailed in Service Bulletin.