



Civil Aviation Authority

PROPOSED AIRWORTHINESS DIRECTIVE



Number: 2013

Issue date: 30 January 2026

In accordance with the CAA Continuing Airworthiness Procedures, the issuance of an Airworthiness Directive (AD) is proposed which will be applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Type Approval Holder's Name:

ACRO AIRCRAFT SEATING LIMITED

Type/Model Designation(s):

Series 6 Passenger Seats

| | |
|-----------------------------|---|
| Effective Date: | [TBD - standard: 14 days after AD issue date] |
| UKTSO Authorisations: | UK.TSOA.00037 Rev 01 |
| Foreign AD (if applicable): | Not Applicable |
| Supersedure: | None |

ATA:25 - Equipment / Furnishings – Passenger Seats – Modification

Manufacturer(s):

Acro Aircraft Seating Limited.

Applicability:

Acro Series 6 Passenger Seats with the part numbers, and where appropriate serial numbers, listed in Appendix 1 to this AD. These are known to be fitted on, but not limited to, A320 and B737 family aircraft.

Definitions:

For the purpose of this AD, the following definitions apply:

Acro: Acro Aircraft Seating Limited.

ASB: Acro Alert Service Bulletin (ASB) ACR-1902-ASB Issue 1 dated 28 Jan 2026.

Affected Seat: Acro Series 6 seats identified at Appendix 1 to this AD.

Affected Rear Foot Fitting (RFF): RFF Part Number (P/N): 14910-3.

Serviceable RFF: RFF P/N: 26517-0.

Reason:

During a dynamic certification test of an Acro Series 6 seat, a Rear Foot Fitting (RFF) experienced a structural failure.

Following an investigation, it was determined that, in the event of an emergency landing or similar event, certain Acro Series 6 seats variants, installed with the affected RFF (P/N 14910-3) could fail to provide their designed safety function presenting a potential unsafe condition in service.

To address this potential unsafe condition Acro have developed a new RFF (P/N 26517-0) and have issued the ASB providing instructions for replacement of the affected RFF.

For the reason described above, this AD requires all affected seats to be modified in accordance with the ASB.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have already been accomplished:

Modification:

Within 24 months of the effective date of this AD modify all affected seats as detailed in ACRO ASB ACR-1902-ASB.

Terminating Action:

Accomplishment of the ASB is considered terminating action to this AD.

Reference Publications:

Acro Alert Service Bulletin ACR-1902-ASB Issue 1 dated 28 Jan 2026.

The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

Remarks:

1. This PAD will be closed for consultation on 28 February 2026.
2. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the CAA aviation safety reporting system [Occurrence reporting | Civil Aviation Authority](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
3. Enquiries regarding this PAD should be referred to: Continued.Airworthiness@caa.co.uk
4. For any questions concerning the technical content of the requirements in this PAD, please contact: Acro Aircraft Seating Limited, Eldon Way, Crick Industrial Estate, Crick, Northamptonshire, NN6 7SL, UK.
Email: productsupport@acro.aero

Appendix 1 to Affected Seat Part Numbers

This Appendix list all the affected Acro Series 6 Seat Part Numbers, and where applicable serial numbers (Table 2 Only), grouped by Component Maintenance Manual (CMM) number:

TABLE 1 - APPLICABLE SEATS - CMM 25-20-63

| Seat Part Numbers | |
|-------------------|-----------------|
| 1210-0601-3-001 | 1210-0604-2-008 |
| 1210-0601-3-002 | 1210-0600-3-009 |
| 1210-0600-3-003 | 1210-0600-3-010 |
| 1210-0600-3-004 | 1210-0602-3-011 |
| 1210-0602-3-005 | 1210-0602-3-012 |
| 1210-0602-3-006 | 1210-0600-3-013 |
| 1210-0604-2-007 | 1210-0600-3-014 |

TABLE 2 - APPLICABLE SEATS – CMM 25-20-70 (ONLY APPLICABLE FOR S/Ns 48526-70461)

| Seat Part Numbers | |
|-------------------|-----------------|
| 1110-0601-3-001 | 1110-0602-3-023 |
| 1110-0601-3-002 | 1110-0600-3-026 |
| 1110-0600-3-003 | 1110-0604-2-027 |
| 1110-0600-3-004 | 1110-0604-2-030 |
| 1110-0600-3-005 | 1110-0602-3-032 |
| 1110-0600-3-006 | 1110-0602-3-034 |
| 1110-0600-3-007 | 1110-0602-3-037 |
| 1110-0600-3-008 | 1110-0605-3-041 |
| 1110-0601-3-009 | 1110-0605-3-042 |
| 1110-0601-3-010 | 1110-0605-3-047 |
| 1110-0600-3-015 | 1110-0605-3-048 |
| 1110-0600-3-018 | 1110-0605-3-049 |
| 1110-0600-3-019 | 1110-0605-3-050 |
| 1110-0602-3-020 | 1110-0601-3-051 |
| 1110-0602-3-021 | 1110-0601-3-052 |

TABLE 3 - APPLICABLE SEATS - CMM 25-20-75

| Seat Part Numbers | |
|-------------------|-----------------|
| 1210-0601-3-015 | 1210-0604-2-030 |
| 1210-0601-3-016 | 1210-0602-3-031 |
| 1210-0600-3-017 | 1210-0602-3-032 |
| 1210-0600-3-018 | 1210-0602-3-033 |
| 1210-0600-3-019 | 1210-0602-3-034 |
| 1210-0600-3-020 | 1210-0600-3-035 |
| 1210-0605-3-021 | 1210-0600-3-036 |
| 1210-0605-3-022 | 1210-0602-3-037 |
| 1210-0600-3-023 | 1210-0602-3-038 |
| 1210-0602-3-026 | 1210-0600-3-039 |
| 1210-0604-2-028 | 1210-0600-3-040 |
| 1210-0604-2-029 | |

TABLE 4 - APPLICABLE SEATS – CMM 25-20-78

| Seat Part Numbers | |
|-------------------|-----------------|
| 1315-0603-3-001 | 1315-0603-3-013 |
| 1315-0603-3-002 | 1315-0603-3-014 |
| 1315-0603-3-003 | 1315-0603-3-015 |
| 1315-0603-3-004 | 1315-0603-3-016 |
| 1315-0603-3-005 | 1315-0603-3-017 |
| 1315-0603-3-007 | 1315-0603-3-018 |
| 1315-0603-3-008 | 1315-0603-3-019 |
| 1315-0606-3-009 | 1315-0603-3-020 |
| 1315-0606-3-010 | 1315-0603-3-021 |
| 1315-0603-3-011 | 1315-0603-3-022 |
| 1315-0603-3-012 | |

TABLE 5 - APPLICABLE SEATS – CMM 25-20-89

| Seat Part Numbers | |
|-------------------|-----------------|
| 1710-0601-3-001 | 1710-0600-3-010 |
| 1710-0601-3-002 | 1710-0602-3-011 |
| 1710-0600-3-003 | 1710-0602-3-012 |
| 1710-0600-3-004 | 1710-0605-3-013 |
| 1710-0600-3-005 | 1710-0605-3-014 |
| 1710-0600-3-006 | 1710-0602-3-017 |
| 1710-0605-3-007 | 1710-0602-3-018 |
| 1710-0605-3-008 | 1710-0600-3-019 |
| 1710-0600-3-009 | 1710-0600-3-020 |

TABLE 6 - APPLICABLE SEATS – CMM 25-20-92

| Seat Part Numbers | |
|-------------------|-----------------|
| 1410-0604-2-005 | 1410-0600-3-026 |
| 1410-0604-2-006 | 1410-0600-3-027 |
| 1410-0605-3-009 | 1410-0600-3-028 |
| 1410-0605-3-010 | 1410-0605-3-029 |
| 1410-0602-3-015 | 1410-0605-3-030 |
| 1410-0602-3-016 | 1410-0600-3-031 |
| 1410-0600-3-019 | 1410-0600-3-032 |
| 1410-0600-3-020 | 1410-0602-3-033 |
| 1410-0601-3-023 | 1410-0602-3-034 |
| 1410-0601-3-024 | 1410-0600-3-035 |
| 1410-0600-3-025 | 1410-0600-3-036 |

TABLE 7 - APPLICABLE SEATS – CMM 25-20-93

| Seat Part Numbers | |
|-------------------|-----------------|
| 1510-0601-3-001 | 1510-0605-3-009 |
| 1510-0601-3-002 | 1510-0605-3-010 |
| 1510-0600-3-003 | 1510-0602-3-011 |
| 1510-0600-3-004 | 1510-0602-3-012 |
| 1510-0600-3-005 | 1510-0602-3-013 |
| 1510-0600-3-006 | 1510-0602-3-014 |
| 1510-0605-3-007 | 1510-0600-3-015 |
| 1510-0605-3-008 | 1510-0600-3-016 |

TABLE 8 - APPLICABLE SEATS – CMM 25-20-95

| Seat Part Numbers | |
|-------------------|-----------------|
| 1015-0603-3-021 | 1015-0603-3-032 |
| 1015-0603-3-022 | 1015-0603-3-033 |
| 1015-0603-3-023 | 1015-0603-3-034 |
| 1015-0603-3-024 | 1015-0603-3-035 |
| 1015-0603-3-025 | 1015-0603-3-036 |
| 1015-0603-3-027 | 1015-0603-3-037 |
| 1015-0603-3-028 | 1015-0603-3-038 |
| 1015-0603-3-029 | 1015-0603-3-039 |
| 1015-0603-3-030 | 1015-0603-3-040 |
| 1015-0603-3-031 | |