

**(I) Bombardier (De Havilland Canada) DHC-7****I Additional Requirements and Special Conditions****1.1 Comparator Warning Indicator**

Comparator warning indicators are required for the two vertical gyro systems and the comparison is to be made at the instrument presentation. The independence of these systems shall not be violated by the comparator. Annunciation must be adjacent to each pilot's ADI.